

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office MON, 23 SEP 18)

Date of writing Report	21 Sept	When handed in at Local Office	21 Sept	Port of	Hull
No. in Reg. Book	Survey held at Boston		Date, First Survey	19 Sept	Last Survey
			19 Sept	19 Sept	1895
1421	on the Machinery of the Wood, Iron or Steel Steamer "Lizzie Annie" Master		19 Sept	19 Sept	1895
Gross Tonnage	99	Net	63	YEAR.	MONTH.
Registered Horse Power	25	Vessel built at	St. Ives	When	1874.
No. of Main Boilers	one	Engines made at	St. Ives	1874	Y
No. of Donkey Boilers		Owners	Boston & London S.S. Co. Lim. Port	Boat	Voyage London
Steam Pressure in Main Boilers	55	If Surveyed Afloat or in Dry Dock	Afloat Boston	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
in Donkey Boilers	9911	(State name of Dock.)		CHARACTER.	Machinery and Boiler Surveys (including date of R.B., if any).
Last Survey No.	927	Port	Hull	Date of last Survey and of Periodical Surveys.	Years Ago

## Particulars of Examination and Repairs (if any) Boston Survey

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

The Main Boiler opened out and examined internally and externally condition good. Safety Valves & Braces Mountings overhauled. Examined under steam and the Safety Valves found to blow at 5.5 lbs per square inch.

## General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 4.04, B.C.M.S. 4.04 or G.L.M.C. 4.04, 140 lb., F.D., &c.)

to remain as classed and to be noted B.S. 9.94 in the Register Book.

Office or Registration Fee (per Sec. 27)	2	Fees applied for	
Survey Fee (per Section 28)	£ 1.0.0	10	R.H.W.
Special Damage Fee (per Section 28)	£ 1.5.0	22	
Travelling Expenses (if chargeable)	£	Received by me,	

James Jones  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

TUES. 24 SEP 1895

Committee's Minute

Assigned

£59.95

© 2018



Lloyd's Register  
Foundation

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD

B.S. 9.95

Brst  
9.95

NOT THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018

Lloyd's Register  
Foundation

LR-PAF-SAL2-63