

Report of Survey for Repairs, &c., of Engines and Boilers.

5 DEC 1934

(Received at London Office)

-6 DEC 1934

Date of writing Report

When handed in at Local Office

Port of

HULL

No. in
Reg. Book.

Survey held at

Hull.

Date, First Survey 24/11/34 Last Survey 1/12/1934

62572 on the Machinery of the Wood, Iron or Steel

Lizzie + Annie

Tonnage Gross 117
Net 64

Vessel built at

hord Shields

By whom

J. Softley + Sons

When 1877-6

Nominal
Horse Power 34

Engines made at

Sodertalje

By whom

Svenska Maskinverken

When 1932

No. of Main Boilers

Boilers, when made (Main)

(Donkey)

No. of Donkey Boilers

Owners B.W. Steamship Tug + Lighter Co. Ltd.

Owners' Address

Port

Hull

Voyage

Steam Pressure in Main Boilers

Managers W. Scott

In Donkey Boilers

If Surveyed Afloat or in Dry Dock

R. Hull

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER
of Special Survey
Date of last Survey and of
Periodical Surveys.Year
assigned
new
survey.Machinery and Boiler
Surveys
(Including date of N.R., if any).H 90 A1 3,32
SS Hul 3rd No 3-4,12.
SS Hul No 2-30.LMC. 9,32.
TS. 6,34.

NE 32

bargo buttons not
fitted.

Oil Fry

Last Report No. 44912 Port Hull.

Advancement

Particulars of Examination and Repairs (if any) of L.M.C.-C.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and sides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the date and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he

offered his services for this purpose, and why they were declined

is a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

is was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

latest date of internal examination of each boiler

the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

screw shaft now been drawn and examined? ho Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

shaft now been changed? If so, state reasons

the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

date of examination of Screw Shaft

State the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

To complete the continuous Survey, the full requirements to be complied with, excepting the examination of propeller, fastenings, sea cocks, main engine cylinders, heads, valves, pistons, con rods, gudgeon pins and crank shaft.

Please see Hull Report 44912.

now done for L.M.C.-C.S.

crank shaft with bearings examined and found good.

Two cylinders (now renewed) examined and found good, fitted in place and engine tried under working conditions.

repairs - wear & tear.

2 cylinders (main engine) renewed. 9 1/8" dia.

General Observations, Opinion, and Recommendation:— The machinery of this vessel as State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&N.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)

now seen is in good condition and eligible in my opinion, to remain as classed with fresh record L.M.C.-C.S. with date, when the survey is completed as stated.

LR-FAF-SALR-300

Survey Fee (per Section 29) L.M.C.-C.S. £ 1 17 6

Special Damage or Repair Fee (if any) (per Section 29.) £ :

Travelling expenses (if chargeable) £ :

Committee's Minute

Assigned Deferred

5 DEC 1934

Received by me

8.3 36

11/3

b. Knoffatt

Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 20 SEP 1935



© 2018

Lloyd's Register Foundation

103 the 4-34 advanced

It is submitted that this vessel WILL BE Liable for the record.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Completion

10/10/34

L. Moffat

