

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

18 FEB 1936

17 FEB 1936

Date of writing Report _____ When handed in at Local Office _____ Port of HULL

No. in Survey held at Hull Date, First Survey 30/12/35 Last Survey 3/2/36
 Reg. Book. 1196 on the Machinery of the Wood, Iron or Steel Sc. "Lysie & Annie" (No. of Visits 26)

Tonnage Gross 117 Vessel built at North Shields By whom J. Softley & Sons When 1877-6 mo
 Net 64 Engines made at Soderstake By whom Svenska Mask. Nya AB When 1932

Nominal Horse Power 34 Boilers, when made (Main) (Donkey)
 No. of Main Boilers ✓ Owners B.W. Steamship, Tug & Lighter Co. Ltd Owners' Address (if not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers ✓ Managers ✓ Port Hull Voyage Coasting
 Steam Pressure in Main Boilers ✓ X Surveyed Afloat or in Dry Dock Union Dry Dock
 in Donkey Boilers ✓ (State name of Dock.) Old Harbour.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) Eng & New Mch.

(Periodical surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

" " Donkey " " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler. ✓

Present condition of funnel(s) ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ , and of the Donkey Boiler? ✓

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? Yes If so, state reasons To suit new engines

Has the shaft now fitted been previously used? No Has it a continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

State date of examination of Screw Shaft _____ State the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft Close fit

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? No

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done (To Owners account) :-

Vessel placed in dry dock. Sea connections opened up and examined. The propeller, sternbush, shafting and engines removed from vessel. Seatings examined, found in good order, and adapted to suit new engines. New engines, shafting, propeller & sternbush, constructed by Messrs Skandia-Verken AB of Lysekil, now fitted to vessel. (See 1st Entry Rpt herewith). A Corderall gland has now been fitted to the new screw shaft. Engine alignment and foundation bolts examined and found satisfactory. Engines examined on completion, tried under working conditions and found satisfactory. An additional starting air receiver has now been constructed and fitted on board. Receiver shell cut from an approved boiler plate marked L.B. N° 844 tested by the Society's Surveyors at Appleby-Frodingham (P.T.O.).

General Observations, Opinion, and Recommendation:—The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0.11, B.&M.S. 0.11, & L.M.C. 0.11, or L.M.C. 140 lb., F.D., &c.)

is now in safe working condition, eligible in my opinion to have fresh record of L.M.C. N.E. 2.36. T.S. (O.G.) N. 2.36. It is further submitted the vessel's name be now deleted from the S.R. list.

Survey Fee (per Section 20) Fee charged on Fees applied for 19
 Special Damage or Repair Fee (if any) ✓ Received by me, 19
 Travelling expenses (if chargeable) ✓

Committee's Minute

FRI. 28 FEB 1936

Assigned LMC 2.36
N.E. 2.36
S.N. 2.36 O.G.

CERTIFICATE WRITTEN
 6.5.36

A.W.B. Edwards
 Engineer Surveyor to Lloyd's Register of Shipping.



© 2018

Lloyd's Register
 Foundation

Iron Sc. M.V. "Lizzie & Annie."

Steel works on 17/3/35. The end plates were made from a piece of boiler plate tested as per enclosed certificate. Receiver hyd. tested to 560 lbs² and found tight and satisfactory. Now stamped LLOYDS TEST 560 LBS². W.P. 280 LBS². B.E. 21.1.36.

The existing air receivers, air piping, & pumping arrangements have been examined, adapted to suit new engines, tried under working conditions and found satisfactory. The oil fuel tanks and fittings have been examined & found in good order.

S.R. list:- Two S.D. steel air receivers, originally fitted in 1932, now hyd tested to 500 lbs² and found tight and satisfactory.

A.W.B.

New propelling machinery
fitted.

It is submitted that
this vessel is eligible for
THE RECORD.

NEW 2:36.
NE 2:36
SN 2:36 O.G.

And particulars

W.R.A.
R.A.
20/2/36.

Handwritten text, likely a technical report or log, detailing vessel specifications and performance. The text is written in cursive and is partially obscured by the printed form on the right.

Rpt. 4b
Date of entry
No. in S
Reg. Book.
11196
Built at
Engines m
Donkey L
Brake Ho
Nom. Hor
Trade for
OIL EN
Maximum pr
Span of bear
Revolutions p
Crank Sha
Flywheel
Tube Sha
Bronze Lin
propeller bos
If the liner
If two liner
shaft Yes
Propeller.
Method of
Measured
Feed.
non-conductin
Cooling Wa
Bilge Pump
Pumps comm
Ballast Pu
Are two inde
Pumps, No.
In Holds, de
Independen
Are all the
led from eas
Are all Sea
Are they size
Are they eac
What pipes
What pipes
Are all Pip
Is the arran
compartment
If a wood
Main Air
Auxiliary
Small Au
Scavengi
Auxiliary
AIR R
Can the i
High Pre
Seamless,
Starting
Seamless,

