

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

23 AUG 1943

Date of writing Report 12/8/43

When handed in at Local Office

16 AUG 1943

Port of Hull

No. in Survey held at Hull

Date First Survey and

Last Survey 30/4/43

(No. of Visits 1)

10404 on the Machinery of the Wood, Iron or Steel

M/V "Lizzie & Annie"

Year. Month.

Tonnage Gross 114

Vessel built at North Shields

By whom J. S. P. & Sons

When 1844

Net 64

Engines made at L. & Y. & Co.

By whom S. & A. & Co. A/B

When

Nominal Horse Power 56

Boilers, when made (Main)

(Donkey)

No. of Main Boilers

Owners B. W. & Co. Ship. Tug & Lighter Co. Ltd

Owners' Address

No. of Donkey Boilers

Managers

(if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers

If Surveyed Afloat or in Dry Dock

Old Harbour

in Donkey Boilers

(State name of Dock.)

Particulars of Classification which must be inserted precisely as in Register Book & Supplements.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
90 A1		LMC 1/38
1/43		LMC (M) 2.41
S.P. Hull N. No 3-1/34		T.S. O.G. 5.43
S.P. Gms No 2-43		
Large ballast tank		Oil Engines
filled		

Last Report No. 21590 Port Gms.

Particulars of Examination and Repairs (if any) Machinery Condition LMC

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If not, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel (S. efficient)

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

State the wear down in the

stern bush

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

Now done:- Starboard air receiver examined internally cleaned together with air pressure pipes found satisfactory

General Observations, Opinion, and Recommendation:- The machinery of this vessel is efficient, in my

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11 *LMC 9.11 or *LMC 140 lb., FD, &c.)

Opinion to remain as classed with fresh record L.M.C 4/43

Survey Fee (per Section 29) £ : : 19

Fees applied for

Special Damage or Repair Fee (if any) £ : : 19

(per Section 29.)

Received by me,

Travelling expenses (if chargeable) £ : : 19

H. C. L. & Co. Surveyors.

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUES. 31 AUG 1943

Assigned

LMC 7/43

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

[Faint, mostly illegible text from the reverse side of the page, appearing as bleed-through.]

At No 2000 742 Ract. 1887 742 Completed

*It is submitted that
this vessel is eligible for
THE RECORD.*

At No. 742

Has

No. 843

