

BS due 11.09 now partly held  
while completed before arrival.  
main boiler examined.

MS is authorized fixed 11.09  
by M.L. B.P. authority from  
the record. BS 12.09 when  
the main boiler safety valve  
have been adjusted.

2/10th.

20.12.09

The Donkey Boiler  
is examined & found to be  
fit for service to be held for \$5.00

if this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

1MUR. 30 DEC 1909

Date of writing Report	28 <sup>th</sup> Dec 1909	When handed in at Local Office	29 <sup>th</sup> Dec 1909	Port of Newcastle-on-Tyne.
No. in Reg. Book.	Survey held at South Shields	Date, First Survey	20 <sup>th</sup> Dec	Last Survey
38	on the Machinery of the Wood, Iron or Steel Vessel		24 <sup>th</sup> Dec 1909	24 <sup>th</sup> Dec 1909
Tonnage	Gross 3708	S.S. "BAKU STANDARD"	Master G. J. Austin	(No. of Plates)
Net	2375	Vessel built at Newcastle	By whom Sir W. G. Armstrong Mitchell When 1893	YEAR. 2
Registered	243	Engines made at Newcastle	By whom Wallend Slip Co. Ltd. When 1893	MONTH.
Horse Power	Boilers, when made (Main) 1893	(Donkey) 1907		
No. of Main Boilers	2	Owners Empire Petroleum Co. Ltd. Port London	Voyage & Laid up	
No. of Donkey Boilers / Steam Pressure		(State name of Boilers)	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
In Main Boilers 160 lbs			CHARACTER.	
In Donkey Boilers 100 lbs			For Special Survey.	

Last Report No. 30386 Port London & Thames Harvey Oil Wharves Ltd

## Particulars of Examination and Repairs (if any) B.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?  Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

Donkey "

 Yes

No, not done.

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?  Yes

To what pressure were they afterwards adjusted under steam?  Not adjusted.

Did the Surveyor examine the Safety Valves of Donkey Boiler?  No

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?  Yes

, and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers?  Yes

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?  Yes

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined?  No

Is it fitted with continuous liner?

or two liners?  or is it without liners?

Has shaft now been changed?  If so, state reasons

Is the shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vitreum of stern bush and top of after bearing of screw shaft?

Not seen.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

To complete the Boiler Survey, the safety valves of Main Boilers require to be adjusted under steam. This will be done before the vessel sails, as she is at present laid up.

Now done. Main Boilers & their Mountings examined & all found in good order

**General Observations, Opinion, and Recommendation:** — The Machinery of this vessel is in good order & safe working condition & eligible in my opinion to remain as classed, with fresh record of B.S. 12-09, when the survey has been completed as above.

Survey Fee (per Section 85). £ 1 - 7 - 0

Fees applied for

20 DEC 1909

Special Damage or Repair Fee (if any) £

(per Section 89.)

Travelling Expenses (if chargeable) £

Received by me,

5/1/10

L. Morris Mann

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.