

New series draft. ok fotted.

7/1. due 1. 17 now held.

It is submitted that

This vessel is eligible for

YUG BINGO D BS 5.12.

NS 5.12.

J.W.
2/5/12

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

OF THE SURVEYS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

LR-FAF-S100-71

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

TUE MAY 7-1912

of writing Report	6 th May	10 12 When handed in at Local Office	6 th May	10 12 Port of Antwerp
in Book.	Survey held at Antwerp		Date, First Survey	16 th April Last Survey
43	on the Machinery of the Wood, Iron or Steel		S. S. "Baku Standard"	1st May 1911 (No. of Vessel)
age { Gross 3708	Net 2375	Vessel built at Newcastle	Master A. Soriano	TEAR. MONTH
Entered 295	Power 2	Engines made at Newcastle	By whom Sir W. G. Armstrong, Middlesbrough 1893	2
Main Boilers 2	Donkey Boilers 1	Boilers, when made (Main) 1893	By whom Wallsend Shipway Co. Ltd. When 1893	
Pressure Main Boilers 160	Donkey Boilers 100	Owners Assured Oil Tanker Co. Ltd. Jacobsen Port London	(Donkey) 1907 Voyage New York	
		If Surveyed Afloat or in Dry Dock Both, Mexico City & Co.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	

Report No. Port

Particulars of Examination and Repairs (if any), B.S. 4 Bond.

Note: Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and these being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

e Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

yes

d. " Donkey "

" Donkey boiler Survey not due Held 1.11 Nov Rpt 5966

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

e Surveyor examine the Safety Valves of the Main Boiler?

yes

To what pressure were they afterwards adjusted under steam? 160 lbs.

f Surveyor examine the Safety Valves of Donkey Boiler?

✓

To what pressure were they afterwards adjusted under steam? ✓

g Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

yes

, and of the Donkey Boiler? ✓

h Surveyor examine the drain plugs of the Main Boilers?

✓

, and of the Donkey Boiler? ✓

i Surveyor examine all the mountings of the Main Boilers?

yes

, and of the Donkey Boiler? ✓

j Crew shaft now been drawn and examined?

yes

Is it fitted with continuous liner? yes or two liners? ✓ or is it without liners? ✓

k Shaft now been changed?

yes

If so, state reasons corroded at after part of liner.

l Shaft now fitted new?

yes

Has it a continuous liner? yes or two liners? ✓ or is it without liners? ✓

m The distance between lignum vitae of stern bush and top of after bearing of screw shaft? rewooded.

Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Whilst in dry dock, - the propeller, stern bush & sea cock fastenings examined and found in good condition. The screw shaft drawn, examined, and replaced by the same one, marked LLOYD'S 3707 N. L.G.S. 10-4-06. The stern bush rewooded in lower half. — The H.P. piston valve chamber bored out & new rings fitted. H.P. bottom end remetalled. M.L. tail rod cut off, piston rings & junk ring renewed. The port side cargo pump renewed.

B.S.: - The two main boilers examined both internally & externally together with their mountings & found, or placed, in good order. Repairs: - The studs through shell for starboard boiler blow down valve renewed. In same boiler, - one hand hole door repaired. A number of tubes in both boilers re-expanded, & some minor repairs effected. The safety valves afterwards adjusted, under steam, to a working pressure of 160 lbs. per square inch.

General Observations, Opinion, and Recommendation: - The machinery of this vessel, as (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9-10, B.&M.S. 9-10, or L.M.C. 9-10, 140 lbs. F.D., &c.) far as now seen, is in good and efficient condition and is, in my opinion, eligible to remain as classed, & to have record B.S. 5-12, and notation "tail shaft new 5-11" in the Register Book.

Survey Fee (per Section 28)

£. s. d.

Special Damage or Repair Fee (if any)

£. s. d.

Traveling Expenses (if chargeable)

£. s. d.

Fees applied for	6/5 1911
Received by me,	10

E. J. Wilvers,
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Record Character of ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Committee's Minute

FRI. MAY 10. 1912

Signed

B. S. 5-12