

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office)

24 FEB 1955

Date of writing Report, 14 Feb. in P.D. When handed in at Local Office.

Port of HAMBURG

No. Reg. Book Survey held at HAMBURG

Date. First Survey and Last Survey, 4th Febr. 1955

72666 on the Machinery of the Vessel or Steel H.V. "PAMIR"

Gross Tonnage	3103	Vessel built at Hamburg	By whom Blohm & Voss	When 1905 10
Net Tonnage	2509	Engines made at Kiel	By whom Fr. Krupp Germaniawrft AG	When 1905 10
MN As Per Rule	180	Boilers, when made (Main)	(Donkey)	-
No. of Main Boilers	-	Owners Landesbank und Girozentrale Schleswig-Holstein	(if not already recorded in Appendix to Register Book)	-
HS "	"	Managing	Port Lübeck Voyage	-
No. of Donkey Boilers	-	If Surveyed Afloat or in Dry Deck	Drydock	Particulars of Classification (which must be inserted
Steam Pressure in Main Boilers	-	(State name of Dock)	Stralsund-Werft	privately as in Register Book & Supplements).
in Donkey Boilers	-			

Last Report No.

Port

Particulars of Examination and Repairs (if any) Docking and T.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this report.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. *No damage*

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey "

If not, state for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain-plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? *Yes*Has it a continuous liner? *Yes*

Is an approved oil retaining appliance fitted at the after end? -

Has shaft now been changed? *No* If so, state reasons

Has the shaft now fitted been previously used? -

Has it a continuous liner? -

Is an approved oil retaining appliance fitted at the after end?

State date of examination of screw shaft *1-2-55*

State the wear down in the

stern bush. *close fit* Is electric light and/or power fitted? *yes*If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? *No*

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by number, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Complete

**NOW DONE:** Vessel placed in dry dock, propeller, stern tube, screw shaft and sea valves and cocks with their fastenings examined and found satisfactory.

(met) due 12.3

## General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this vessel, where now seen, is in efficient condition and eligible, in my opinion, to remain as now classed with fresh record of TS CL 2.55.

Survey Fee (per Section 23). T.S.	£ DM 30,-	Fee applied for, 22.2.1955	<i>P.F. Foster</i>
Special Damage or Repair Fee (if any) (per Section 23)		Received by me,	Engineer Surveyor to Lloyd's Register of Shipping.
Travelling expenses (if chargeable)	£ DM 10,-	TUESDAY 5 APR 1955	

Committee's Minute.

Assigned

As now

S 2.55 - not posted - see on 18/4/55

Insert character of Ship and Machinery precisely as in the Register Book

A Certificate required if so, to be sent to



© 2018

Lloyd's Register  
Foundation