

Dates of Survey while building During progress of work in shops - - - - -
During erection on board vessel - - - - - 12,17,18/12/51 ; 3,8,16,17 + 18/1/52
Total No. of visits 8

Dates of Examination of principal parts—Cylinders - - - - - Covers - - - - - Pistons - - - - - Piston rods - - - - -

Connecting rods - - - - - Crank and Flywheel shafts - - - - - Intermediate shafts - - - - -

Crank shaft Material S.M.Steel Tensile strength forwd.engine No.14101:Best.No.2358
Elongation See gd Cont. attached. Identification Marks aft engine No. 14100:Best.No.1774, 92379 DEW, 15

Flywheel shaft, Material - - - - - On Cylinder Covers: 5/75 ATU, 104 51

Identification marks on Air Receivers 6 21422 H, Nos. 10000, 10002, 10008, 10009, On Cylinder Blocks:Germanischer Lloyd,15318
10010, 10011, 114 51, Cl PD. 60 atü, BDR Germanischer Lloyd,15279
30,atü. Inh. 320 ltr.

one auxiliary air receiver: OH 47448, 12.51, 144/3

Is this machinery duplicate of a previous case. yes If so, state name of vessel "PAMIR"

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.) These generator sets have been built and hydraulically tested under the survey of Germanischer Lloyd.

These engines have now been opened out and examined internally, two cylinder covers tested hydraulically with satisfactory results. The workmanship and the material appear good. The generator sets have been satisfactorily unstalled on board the vessel and subsequently examined under working conditions and found in good order.

These generator sets are eligible in my opinion to be classed with the notation LMC 1.52 without distinguishing mark *.

The amount of Fee ... £ : : When applied for 19
Travelling Expenses (if any) £ : : When received 19
See Report 8 (No. 368)
Committee's Minute
Assigned
TUES. 1 JUL 1952
Surveyor to Lloyd's Register of Shipping.
b. Chamber

Rpt. 13.
Date of writing Report
No. in Surveyor's Register Book
22171 on
Built at
Owners
Installation
Is vessel equipped
Plans, have the
Heating
Prime Movers,
with a trip switch
Are the generators
Have machines
under 100 kw.
and aft tank
is the ventilation
damage from
are they in accordance
steam and oil
material is it in accordance
per Rule
for each generator
equalizer,
and the switch
Are compartment
ammeters
protection devices
Switches, Circuit
make of fuses
overload do the
devices operate
if otherwise than
under maximum
Are all the cables
damage yes
type of cables (if any)
and laundries
Are all lead sheaths
bulkheads provided
effectively bushed
Have refrigeration
Are the motors and

3m.651.-T. (MADE AND PRINTED IN ENGLAND)
(The Surveyors are requested not to write on or below the space for Committee Minutes.)