

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

TUE JUL 20 1920

Date of writing Report	28-6-20	When handed in at Local Office	29-6-20	Port of Leith	
No. in Reg. Book.	Survey held at Leith		Date, First Survey	May 12	
27086	on the Machinery of the Wood, Iron or Steel		Last Survey	7/6/1920	
Tonnage	Gross 576	Net 528	No. of Years 4	YEAR MONTHS	
Registered Horse Power	96		By whom Boardaytire 16	When 1964-11	
No. of Main Boilers	1		By whom Hawkhorn 10	When 1909	
No. of Donkey Boilers	1		(Donkey) 1689	1909	
Steam Pressure - in Main Boilers	150		Voyage		
in Donkey Boilers	50		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
				CHARACTER of Special Survey, Date of last Survey and of previous Surveys.	Machinery and Boiler Surveyor (including date of R.B. if any)
				+ A	L.M.C. 6-1920
				10-18	+ N.D. 12-1920
				9/6 4-103-6-15	B.S. 10-16
				7/6 89	T.S.N. 9-17
				N.D. 50	

Last Report No. Port

Particulars of Examination and Repairs (if any) L.M.C.

*Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Dismantlings and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and, besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.*

Is damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

150 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

50 lbs

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boiler?

Yes

, and of the Donkey Boiler?

Yes

Did the Surveyor examine the drain plugs of the Main Boiler?

None

, and of the Donkey Boiler?

None

Did the Surveyor examine all the mountings of the Main Boiler?

Yes

, and of the Donkey Boiler?

Yes

Has screw shaft now been drawn and examined?

Yes

Is it fitted with continuous liner?

No

or two liners?

Yes

or is it without liners?

Has shaft now been changed?

No

If so, state reasons

Is the shaft now fitted new?

Has it a continuous liner?

or two liners?

or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

Rewooded

If Survey is not complete state what arrangements have been made for its completion and what remains to be done.

Complete

Now done. The cylinders, pistons, slides, all pumps, condenser, crank, thrust, tunnel, & propeller shafts, sea cocks, pipes, bilge suction, roses & details examined. Repairs. H.P. piston rod, M.P. & L.P. valve spindle rods skinned up, new neck rings & glands rebushed. L.P. piston spring renewed. H.P. crank pin bearing metallized, including one thrust collar. M.P. slide valve face true'd up. Few pump rods skinned up, new neck rings & glands rebushed. Air pump bucket re-packed. Two new delivery valves for bilge pump fitted. The main & donkey boilers with their mountings examined throughout, the following parts repaired by the electric welding process. The landings at centre b. b. front & back circumferential seams at bottom of main boiler. Renew 5 bars in port wing furnace, & 5 in starwing furnace. Two new manhole doors fitted.

The main & donkey boilers with their mountings examined throughout, the following parts repaired by the electric welding process. The landings at centre b. b. front & back circumferential seams at bottom of main boiler. Renew 5 bars in port wing furnace, & 5 in starwing furnace. Two new manhole doors fitted.

## General Observations, Opinion, and Recommendation:—

P.T.O.

*Specify what alterations, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.; thus, for example, B.S. 9-11, B.A.-M.S. 9-11, or Q.L.M.C. 9-11, 140 lb., F.D., etc.)*

This vessel's machinery is eligible in my opinion to remain as classed with fresh record of L.M.C. 6-20 valid T.S. 6-20

Fee (per Section 84)

3 10 -

Fee applied for

200 10-20

Actual Damage or Repair Fee (if any)  
(per Section 84.)

Received by me,

Travelling Expenses (if chargeable)

19

Committee's Minute

TUE JUL 6 1920

L.M.C. 6-20

L.M.C. 6-20

15-7-20

*C. J. Williamson*  
J. R. Williamson  
Engineer Surveyor to Lloyd's Register of Shipping.

In a certificate required if so to be sent



© 2018

Lloyd's Register  
Foundation

St. Vincent 6.19 numbered  
and photographed repairs to engine  
boiler.

It is submitted that  
this vessel is eligible for  
T.R.B. and G.D. L.M.C. 6.20

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

Main steam pipe annealed & tested to 175 lbs pressure & found satisfactory.  
In the donkey boiler a small patch in way of front circumferential  
at bottom removed & plate in the vicinity of same where water made  
up by welding. All safety valves adjusted under steam.

J.R.W

5.6.20

J.R.W

5.6.20



© 2018

Lloyd's Register  
Foundation