

# REPORT of SURVEY for REPAIRS, &c.

SAT 2 APRIL 1887

No.

No. in Survey held at London.

Date, First Survey 1<sup>st</sup> Feb<sup>rd</sup> Last Survey 1<sup>st</sup> April 1887

(No. of Visits)

235 on the Composite Ship "Thermopyle".

Master Allan - S - S 4

YEAR MONTH

TONNAGE:— Built at Aberdeen

By whom W. Hood & C:

NET 0.45

Owners L. Thompson & C:

GROSS 19.9

Owners' Address

When 1868.

UNDER DRY. 0.27 (If not already recorded in Appendix to Register Book.)

Port belonging to Aberdeen.

If Surveyed Afloat or in Dry Dock Dry Name of Dock Ratcliff, Cross Destined Voyage Sydney

Length of Poop

ft. of Forecastle

ft. of Raised Or. Deck

ft. Moulded Depth

ft. ins.

(If these particulars are not yet recorded in the Register Book.)

Character in Register Book.

Last Survey, No. 44582 Port LON

H.T. LON. S. S. LON. SH.

1.95

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard  
Repairs on account of Damage should be separated from Repairs due to other causes. State also the date and Initials  
of any letters respecting this case.)

in salt water ft.  
as painted on Ship in fresh water ft.  
ft. ins.  
ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE

for Continuation. Section 45.

This vessel was placed in Dry Dock, on good high blocks. The sheathing having been removed, the caulking of the bottom and toprises was tested. The bottom has been recaulked and remated over felt.

The planks of one stroke from amidship to stem on the starboard side and from amidship to stern on the port side were removed, exposing the bilge plates, diagonal plates and the backs of the frames. Five frames aft on the port side were found to be slightly corroded. Doubling frames from five to six feet long have been fitted as compensation. The bilge plates, diagonal plates and other iron work exposed were in good order. A plank in way of the non sheer stroke plate was removed and the plate found in good order.

All the outside planking from the light water mark upwards, scraped, was rubbed bright and found in good order.

A considerable number of bolts were driven out on both sides of

PRESENT CONDITION OF THE DECKS	Wood	Plank (Bottom) & Counter	Wood	Ceiling	Wood	Boats	Wood
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"	Condition, how ascertained examined	
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Balls	Wood
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (If Iron Ship)	"	Anchors No. of 30. 15. 24.	
Plankshears	"	----- ditto ----- at other places	"	Caulking of Bot'm, Dk', & Waterways	"	Cables Ranged (2704) Wood	
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. Y.M. on Felt	"	Hawsers & Warps Suitable	
Toprises	"	Clamps & Bolts	"	When put on	"	Standing & Running Rigging Wood	
Wales	"						
Engine-Room Skylights	Wood	Coal-Bunkers, Openings, Lids, &c.	Wood	Scuppers	Wood	Cargo & Main Hatchways	Wood
							Hatches "

General Observations, Opinion as to Class, &c.:

This vessel has been especially surveyed as above described and found in sound and efficient condition, eligible in our opinion to remain as classed and to be continued A1 3 Years

from 1887

Entry Fee (if chargeable) per Scale I, Sec. 27. £ 3 - - -

Office Fee (if chargeable) per Scale II, Sec. 27. £ 7 - - -

Survey Fee (per Section 28) £ 7 - - -

Special Damage Fee (if any) (per Sec. 28) £ 1 - - -

\* Certificate if required to be sent as per margin £ 5 - - -

Travelling Expenses (if chargeable) £ 1 - - -

Second Surveyor's Fee (if any) £ 1 - - -

Committee's Minute £ 1 - - -

Character assigned

received by me,

15/4/1887

THURS. 7 APRIL 1887

Allison R. Wilson.

N.C.S. Isaac

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2018

Lloyd's Register  
Foundation

The vessel. A few of the iron bolts were slightly corroded, all the iron bolts which were removed have been renewed.

All the close ceiling was removed and the frames, floors and all iron work in the holds were cleaned sealed and painted.

The cement was entirely removed from several bays exposing the frames, floors and outside planking &c. Six floor plates in the vicinity of the fresh water tanks were found to be badly corroded in way of the timber holes, six new doubling plates about five feet long have been fitted as compensation. The cement has been renewed and repaired where necessary, and the floors, frames, iron keel plate &c are now in good order.

The ceiling has been renewed and repaired where necessary.

The decks were hored and found in good order and of suitable thickness.

The fore and main masts have been reduced in height five feet. The following masts and spars have been renewed. Main and mizzen topmasts. Fore and main topgallant masts, fore topmast, lower main topsail yard, lower mizzen topsail yard, upper fore topgallant yard and crossjack yard. All other masts, spars and rigging &c have been overhauled and made good.

The windlasses was stripped and examined, and found in good order.

The chain cables were ranged (270 fathoms) and found in good order.

Allison P. Wilson.

M. B. C. Daney