

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

JUN 5 JUN 1899

Date of writing Report *June 1st 1899* When handed in at Local Office *June 1st 1899* Port of *Antwerp*
 No. in Reg. Book *103* Survey held at *Antwerp* Date, First Survey *May 15* Last Survey *May 15* 1899
 on the Machinery of the *Wood, Iron or Steel* *33* *Nederland* Master *Opfeld*
 Tonnage Gross *2276* Net *2158* Vessel built at *Newcastle* By whom *Palmer & Co* When *1875* 6
 Registered Horse Power *352* Engines made at *Newcastle* When *1875* Boilers, when made (Main) *1875* (Donkey)
 No. of Main Boilers *2* Owners *Doc. Anon. Belg. American Port Antwerp* Voyage *Philadelphia*
 No. of Donkey Boilers *1* Surveyed Afloat or in Dry Dock *Rhiniquai* Particulars of Classification (which must be inserted
 Steam Pressure in Main Boilers *4.5* (State name of Dock.)
 in Donkey Boilers *4.5*

Last Survey No. *4049* Port *Ant*Particulars of Examination and Repairs (if any) *Comp. B.S.*

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the nature of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the date and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Donkey Boiler & its Safety Valve examined & the latter adjusted under steam.

General Observations, Opinion, and Recommendation: *This vessel's Boilers*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and state any alteration required to be made in the records of the vessel's machinery, boilers, working pressure, &c.; thus, for example, B.S. 9, 97, B.S. 9, 97 or Q.L. 9, 97, 140 lb., F.D., &c.)

are now in good safe working condition & eligible, in my opinion, to remain as classed with notation of BS 4.99

Office of Registration Fee (per Sec. 27)

£

Survey Fee (per Section 28)

£

Special Damage Fee (per Section 28)

£

Travelling Expenses (if chargeable)

£

State if Certificate is required

Yes

Committee's Minute

Assigned

Fees applied for

46 1899

Received by me,

*46 1899*CERTIFICATE
WRITTEN

A. Ruck Keene
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

TUES. 6 JUN 1899

BS. 4.99



© 2018

Lloyd's Register
Foundation

Report of Survey for Reports, &c., of Engineers and Builders

NOTE.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much slumped as to spread the ink, or cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

THESE REPORTS ARE NOT TO BE USED FOR ANY OTHER PURPOSE

THESE REPORTS ARE NOT TO BE USED FOR ANY OTHER PURPOSE

5/6/99