

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

SAT. 26 AUG. 1899

Date of writing Report	Aug. 25 th 1899	When handed in at Local Office	Aug. 26 th 1899	Port of	Antwerp
No. in Reg. Book.			Date, First Survey	and	Last Survey Aug. 21 st 1894
Survey held at	Antwerp				
112 on the Machinery of the Wood, Iron or Steel S.S. "Nederland"					
Gross 2876					
Tonnage					
Net 2153	Vessel built at	Newcastle	By whom	Palmer's Co.	When 1870 6
Registered Horse Power 352	Engines made at	do.	do.	Boilers, when made (Main) 1873 (Donkey) 1873	
No. of Main Boilers 2	Owners Soc: Amor. Belg. American	Port	Antwerp	Voyage Philadelphia	
No. of Donkey Boilers					
Steam Pressure in Main Boilers 75	If Surveyed Afloat or in Dry Dock	City dry dock	Particulars of Classification (which must be inserted (State name of Dock.)		
in Donkey Boilers 60					

Last Survey No. Port

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the name of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes) and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the date and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

Donkey

"

"

"

✓

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

✓

To what pressure were they afterwards adjusted under steam?

✓

Did the Surveyor examine the Safety Valves of Donkey Boiler?

✓

To what pressure were they afterwards adjusted under steam?

✓

Has the propeller shaft been drawn and examined at this time?

No

If spare propeller shaft fitted, state whether new?

✓

State the distance between ligament of stern bush and top of after bearing of screw shaft?

1/8 inch.

✓

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

The stern bush, sea-cock and propeller fastenings examined and found in good order -

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.: thus, for example, B.M. 9.97, B.A.N.S. 9.97 or Q.L.M.C. 9.97, 140 lb. P.D., &c.)

The machinery, so far as seen, is in good condition eligible in my opinion to remain unclassed in the Register Book.

Office or Registration Fee (per Sec. 27)

£

Fee applied for

Survey Fee per Section 28

£

10

Special Damage Fee (per Section 28)

£

Received by me,

Travelling Expenses (if chargeable)

£

10

State if Certificate is required

✓

Committee's Minute

TUES. 29 AUG 1899

Assigned

as now

H.P. Cornish
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

P.S.—If this Report is copied by Copyright Press, special care must be taken that the writing paper is not so much dampened as to spoil the ink, or cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

H.M.O.
21/1/22.

OF THE SURVIVORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

