

No. 5034

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	Sept 17 th 1901	When handed in at Local Office	Sept 17 th 1901	Port of	Antwerp	(Received at London Office)	SAT. SEP 21 1901
No. in Book	76	Survey held at	Antwerp	Date, First Survey	Sept 2 nd	Last Survey	Sept 12 th 1901
Gross	2610	on the Machinery of the Wood, Iron or Steel	5/8 " Nederlaand "	Master	H. J. Geesbergen	6/1901	
Net	1900	Vessel built at	Newcastle	By whom	Palmer's Co.	When	1873-6
Entered	52	Engines made at	do:	When	1873	Boilers, when made (Main)	1873 (Donkey) 1873
Main Boilers	2	Owners	Mr. Amon de Neuf Belg.-American	Port	Antwerp	Voyage	New York.
Donkey Boilers	1	If Surveyed Afloat or in Dry Dock	At 6 m, over	(State name of Dock.)			
Pressure	75						
Main Boilers	45						
Donkey Boilers	45						

t Survey No. Port

Particulars of Examination and Repairs (if any) Annual Overhaul + 100 A.I.		CHARACTER of Survey Date of last Survey and of Previous Surveys
		Machinery and Boiler Surveys (including date of R.B. if any)
2-01		U.S. 2.97
N.Ant. 2-10. 3.7.97		B.P. 8.00
Yes		
Yes		
-		
-		
-		
To what pressure were they afterwards adjusted under steam?		75 lbs per sq. in.
To what pressure were they afterwards adjusted under steam?		45 lbs per sq. in.
If spare propeller shaft fitted, state whether new?		
The distance between ligament of stern bush and top of after bearing of screw shaft?		1/8 inch.

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

The main boiler, superheater & safety valves examined & found in good order excepting a patch in saddle of port furnace, 1st boiler, which has been extended -

The safety valves blow at 75 lbs per sq. in.
Examined donkey boiler & its safety valves. Gauges checked,
C.C. furnace. Found boiler in safe-condition for a working pressure
of 45 lbs per sq. in. which should be noted in the Register Book.

Adjusted safety valves to blow at 45 lbs per sq. in.

Examined cylinders, pistons, slides, pumps, sea-cocks,
crank, thrust & screw shafting.

All the valve gear motion overhauled & readjusted.

The condenser tested. The stern bush, sea-cock & propeller
fastenings examined & found in good order.

Also see Antwerp Report No. 4776.

General Observations, Opinion, and Recommendation:-

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.: thus, for example, D.N.C. 9.00 or Q.L.M.C. 9.00,
140 lbs. F.D., etc.

The machinery & boilers are in safe-working condition
eligible in my opinion to remain as classed and
to have **D.L.M.C. 9.01** recorded in the Register Book.

Registration Fee (per Sec. 87)	£ 6.6.0	Fee applied for	17/9/1901
Tax (per Section 88)			18 P.C.
Damage Tax (per Section 89)		Received by me,	
or Expenses (if chargeable)		17/9/1901	

A. F. Gorrie

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate to be sent to
Committee's Minute

TUES. SEP 24 1901

TUES. NOV 5 1901

TUES. 10 DEC 1901

TUES. DEC 4 1901

© 2018



Lloyd's Register
Foundation

Small Bridge up river

N.B.—If this Report is copied by Copying Press, especially care must be taken that the copying paper is not so much stamped as to offend the ink, or to cause it to show through to the other side.

It is understood that
this record is suitable for
THE RECORD

B. & M. I. 9.0

Ms. form to be used
for this.

2/1/10

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2018

Lloyd's Register
Foundation