

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	Dec 3 40	When handed in at Local Office	Dec 3 40	Port of New York		
No. in Reg. Book	Survey held at Hoboken N.J.		Date, First Survey	13 th Nov	Last Survey	18 th Nov 1940
Reg. Book No. 69226	on the Machinery of the Wood, Iron or Steel M.V. AGNITA		(Received at London Office)		(No. of Visits)	14
Tonnage Gross 3552.	Vessel built at Newcastle	By whom Hawkhorn Leslie & Co Ltd.	Year. Month.	1931	5	
Net 2019.	Engines made at Amsterdam	By whom Werkspoor		When 1931		
Nominal Horse Power 476.	Boilers, when made (Main)	(Donkey) 1931				
No. of Main Boilers 1	Owners Anglo-Saxon Petroleum Co Ltd.	Owners' Address				
No. of Donkey Boilers 1	Managers	Port Voyage				
Steam Pressure in Main Boilers ✓	Surveyed Afloat AND in Dry Dock Tietjen Lang & Co.					
In Donkey Boilers 150	(State name of Dock.)					

Last Report No. Port

Particulars of Examination and Repairs (if any) Taking Repairs.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

Yes

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Nov 15th

Present condition of funnel(s)

Good.

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes. To what pressure were they afterwards adjusted under steam? 150 lbs.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ and of the Donkey Boilers? Yes.

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? Yes.

Did the Surveyor examine all the mountings of the Main Boilers? ✓ and of the Donkey Boilers? Yes.

Has screw shaft now been drawn and examined? Yes. Is it fitted with continuous liner? Yes. Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

Has shaft now been changed? Yes. If so, state reasons Surface of liner in poor condition.

Has the shaft now fitted been previously used? Yes. Has it a continuous liner? Yes. Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated? ✓

State date of examination of Screw Shaft Nov 13th. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Close.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and power fitted Yes.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done C.S.

Inward The Vessel placed in dry dock, propeller, stern tube & its fastenings, and the fastenings of the sea connectors examined & found in good order.

The Tail shaft drawn for examination, liner of shaft found in bad condition in way of stuffing box. The Stern tube rewooded and the used spare tail shaft fitted, in good order. One propeller blade slipped at tips, brayed & dressed up.

L.M.C.-C.S. Main engine No. 3 Cylinder, liner, lead, piston, rod, valves & gear. Nos 1, 2 & 4 Clutch shaft journals & bearings. Port starting air tank, internally. The Main engine blast air bottle, internally. Main engine piston cooling water pump all examined in good.

D.B.S. The donkey boiler examined intact with valves & intgs. The boiler examined under steam & its safety valves adjusted. Steam pipes found good when exposed. S.P. Liner End user examined, 70 tubes ruptured. Condenser tested. Water not received at this time. Condenser efficient meantime.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.; thus, for example, B.S. 9.11, B.&M.S. 9.11, & L.M.C. 9.11, or D.B.S. 140 lb., F.D., etc.)

The Machinery of this vessel is eligible, in my opinion to remain as classed with fuel record of + L.M.C.-C.S. (with date) when the Survey has been completed, also D.B.S. 11-40 and Tail shaft seen 11-40.

Survey Fee (per Section 29)	L.M.C.-C.S. \$25.00	
Special Damage or Repair Fee (if any) (per Section 29)	D.B.S. 15.00	Fees applied for 10
Travelling expenses (if chargeable)	£ 20.00	Received by me, 19

Committee's Minute NEW YORK DECEMBER 1940

Assigned As now D.B.S. 11-40 T.S. 11-40

Subject: D.B.S. 11-40 T.S. 11-40

M. Belton.
Engineer Surveyor to Lloyd's Register of Shipping.



© 2018

Lloyd's Register Foundation

This image shows a single page of a document that has been severely redacted with black ink. The original text is mostly illegible but appears to be a formal letter or report. A large portion of the page is covered by a large, roughly rectangular redaction mark. In the bottom left corner, there is a vertical column of handwritten text that reads: "Noted Subject & matter for State conference being discussed. At first opportunity." Below this handwritten note is a signature that appears to be "J. H. A." followed by the date "4/1/41". The rest of the page contains faint, illegible text that is likely part of the original document's content.

Collected
Subject matter for of these
condemned being discussed.
at first opportunity.

LR-FAF-T813-412

תְּמִימָנָה וְעַמְּדָה



© 2018

Lloyd's Register
Foundation