

No. 11959

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report.

IS When handed in at Local Office.

IS

Port of Glasgow

28 DEC 92

No. in Reg. Book.

Survey held at Glasgow

Date, First Survey 21 December

Last Survey 23 December 1892

on the Vessel "City of Agra"

(No. of Visits)

Master W. M. Greene

TONNAGE:

GROSS 3274

UNDER Dk. 3109

NET 2133

Built at Glasgow

YEAR.

By whom C. Councill & Co

When 1879

Owners G. Smith & Sons

Port belonging to Glasgow

Owners' Address

Surveyed Afloat or in Dry Dock? Yes Name of Dock Govan

(If not already recorded in Appendix to Register Book.)

WB=DAW tons; f tons; uE&B tons; CellDB tons;

FPT tons; APT tons; MT tons.

Destined Voyage Calcutta

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.

For Special Survey, Date of last Survey and of Periodical Surveys.

Anticipated New Survey.

(including date of N.S., if any).

Machinery and Boiler Surveys

(including date of N.S., if any).

-100A1 1-92 6-91

SS N3 566-91 NE8B 6-91

Last Survey, No. 3200 Port

Hin

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

This vessel has been placed upon blocks in dry dock and the bottom examined, cleaned and coated. Cast Steel Clamps pieces three inches thick, have been fitted on each side, at the bottom of stern frame on account of the flattening at the keels (Certificates of the castings attached hereto). The bottom plate on the port side of mader renewed; the mader lifted and the bottom pintle rebrushed. The chain cables, ranged found complete and in good condition.

Bottom part of stem name

Repaired - Rudders repaired

N.B.—All alterations in the existing records should be underlined.

✓