

52293

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FRI 4 SEP 1891

No.	Date of Writing Report. 14. 9. 91	Port of	
No. in Reg. Book.	Survey held at London on the Machinery of the S. S. Aberdeen	Date, first Survey Aug. 26 Last Survey Sept. 3 1891	
28		Master	
Tonnage	Gross 3616 Net 2371	No. of Visits 4 YEAR. MONTH.	
Registered Horse Power	400	Vessel built at Helgoland Engines made at do	By whom P. Napier & Sons When 1881 Boilers, when made (Main) 1881 (Donkey) 1881
No. of Main Boilers	2	Owners G. Thompson & Co.	Port Aberdeen Voyage
Steam Pressure— in Main Boilers	110 lbs.	N Surveyed Afloat & in Dry Dock Albert.	Class of Vessel & Machinery 1-100 A 1.
in Donkey Boiler	65.	(State name of Dock.)	(As in Register Book, including dates of 1. I.M.C. 2.90 Special Surveys of Ship and B.S. 8.90 of last Boiler Survey.)
Last Survey No.	51534 Port. Lon		S.S. Lon. No 2-90

Particulars of Examination and Repairs (if any) Annual B. S.

(State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

Donkey "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Vessel placed in dry dock, sea connections exd. & found to be in good condition. One blade of propeller found to be broken & two bent, all the blades have now been renewed. Tail shaft down $\frac{1}{4}$ Main boilers exd. internally & externally & found in good condition. Safety valves in good condition. Wunch boiler exd. & found Main safety valve lifted at 110 lbs. Wunch 65.

ACHTUNG

General Observations, Opinion, and Recommendation:—The boilers being now in good condition, renders the vessel eligible in my opinion to remain as classed than the notfmr. B. S. 9. 91 recorded.

Office or Registration Fee (per Sec. 27) £ 1 - 0 -

Fees applied for

3791 1891

Survey Fee (per Section 28) £ 2 - 0 -

Received by me,

16/9 1891

Special Damage Fee (per Section 28) £ 0 - 0 -

Travelling Expenses (if chargeable) £ 0 - 0 -

Geo. F. Melvinson,
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required

Committee's Minute

FRI 11 SEP 1891

Assigned 1889/91

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to bleed through to the other side.

It submitted that this vessel
is eligible & have B.S.G.-91

M.A.
10-9-91

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.