

No. 5534

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 14th April 1894 When handed in at Local Office

No. in Reg. Book Survey held at London.
857 on the Port D. Br.

Tonnage Gross 3564
Net 2329
Registered Horse Power 299
No. of Main Boilers 2
Steam Pressure in Main Boilers 160.
in Donkey Boiler 100.

Vessel built at W. Hartlepool By whom W. Gray & Co. (Linn). When 1892.
Engines made at Do. When 1892. Boilers, when made (Main) 1892 (Donkey) 1892.

Owners M. Samuel & Co. Port London. Voyage

Date, First Survey 18th Jan. Last Survey 9th April 1894
S. S. "Murex" Master J. Barry.

(Received at London Office 17 APR. 94)

18 Port of London

YEAR MONTH

CHARACTER
for Special Survey,
Date of last Survey and of
Periodical Surveys.

Years
Survey
Anched
now
expired.

Machinery and Boiler
Survey
(including date of N.B., if any).

+100 A.I.
1.94
Carrying petroleum in bulk

+G.M.C.
7.92

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

Particulars of Examination and Repairs (if any) Repair of D.B.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Do. " Donkey " "

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? No

At what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? No

To what pressure were they afterwards adjusted? Not adjusted.

If the Survey is not complete state what arrangements have been made for its completion? D.B. to be refitted on board on vessels' arrival - time not stated.

The fire-box of the Port Donkey boiler having partly collapsed, the boiler was taken ashore and the fire box removed, faired and re-riveted and six 1½" stays fitted in lower part where faired. The boiler was tested by hydraulic pressure to 150 lbs and, in our opinion, is now safe for the original pressure of 100 lbs.

General Observations, Opinion, and Recommendation:— The above is reported for the information of the Committee.

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey:
thus, for example, P.S. 9.92, B.G.M.S. 9.92 or G.M.C. 9.92, as the case may be.)

Office or Registration Fee (per Sec. 27).....	£	1	1	Fees applied for
Survey Fee (per Section 28).....	£	1	1	18
Special Damage Fee (per Section 28).....	£	1	1	
Travelling Expenses (if chargeable).....	£	1	1	18

Mr Salmon & R. Elliott
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required

Committee's Minute

FRI 20 APR 1894

Assigned

As now

~~the~~ ~~which~~ ~~holes~~ ~~have~~ ~~been~~
~~drilled~~ ~~remain~~ ~~spherical~~, ~~but~~ ~~it~~
~~is~~ ~~not~~ ~~possible~~ ~~to~~ ~~get~~ ~~them~~ ~~out~~

~~This~~ ~~vessel~~ ~~is~~ ~~entirely~~
~~constructed~~ ~~of~~ ~~CLAY~~ ~~BRICKS~~

J. M.
W. H.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.