

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

of writing Report 3rd October 1917, When handed in at Local Office

to Port of Kobe 15/8, 17/8.

in Book Survey held at Kobe. Date, First Survey 2/8, 4/8, 9/8 Last Survey 11/8, 14/8, 19/17

on the Machinery of the Wood, Iron or Steel Twin Screw Steamer "HITACHI MARU" Master S. Tominaga (No. of Visits Seven)

Gross 6557 T.R.A.C. MONTH.

Net 4039 Vessel built at Nagasaki By whom Mitsu Bishi D. &amp; E. Works. When 1906 12

Power 631 N.H.P. Engines made at do By whom do When do

Main Boilers 4 Boilers, when made (Main) 1906 (Donkey) ----

Donkey Boilers Pressure 200 lb. Owners Nippon Yusen Kabushiki Kaisha Port Tokio Voyage

Main Boilers 200 lb. If Surveyed Afloat or in Dry Dock Mitsu Bishi dry dock. Particulars of Classification (which must be inserted  
(State name of Dock.)

presently on the Register Book or Supplements).

CHARACTER.  
for Special Survey.  
Date of last Survey and of  
Previous Surveys.Machinery and Boiler  
Survey (including date of E.S. if any).

#100A 1 2,17 \*LMC 11,14

ssYka. No. 2-14 B.S. 8,16

Shafts seen

P11,15, S2,17

st Report No. Port

Particulars of Examination and Repairs (if any)

Special Surveys, when held, must be reported in detail and serial in the terms of the Rules. State clearly the  
use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on  
account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and  
do not being detailed in the body of the report, should be briefly summarized at the end of the report. State also the  
date and initials of any letters respecting this case.Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were  
declined?

Was a damage report made by anyone else? If so, by whom?

Does Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

O. Donkey " " " None

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Does Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 205 lbs

Does Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Does Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boiler?

Does Surveyor examine the drain plugs of the Main Boilers? None , and of the Donkey Boiler?

Does Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boiler?

Screw shaft now been drawn and examined? Yes Is it fitted with continuous liners? Yes or two liners? or is it without liners?

Screw shaft new been changed? Yes If so, state reasons. No defect. In use a long time.

Screw shaft now fitted new? Yes, both Has it a continuous liner? Yes or two liners? or is it without liners?

The distance between lignum vitae of stern bush and top of after bearing of screw shaft? Lignum vitae renewed.

Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Boilers and mountings examined and found good.

Cylinders, pistons, valves, rods, condensers, pumps and sea connections overhauled examined and found in order.

Inboard shafting good.

Both propeller shafts drawn and on account of age replaced by the two spare shafts of Morrison's "Lockfest iron" having continuous liners and each stamped R.W. &amp; Co. Makers' Nos.

LLOYDS 404 &amp; 405

No. 4307

T.L.T. 30/12/05

30/12/05

## General Observations, Opinion, and Recommendation:

Note  
State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; there, for example, B.S. 8,11, B.W.G. 8,11, or G.B.M.C. 8,11, 160 lb., F.D., &c.)

The machinery is now in good condition and eligible in my opinion for the records \*LMC 8,17

and Both propeller shafts renewed 8,17.

Fee (per Section 88) Yen 180.

Damage or Repair Fee (many) (per Section 88)

Drawing Expenses (if chargeable)

Fees applied for	Aug. 24 <sup>th</sup> 17
Received by me,	Aug. 27 <sup>th</sup> 17

A. H. Jones  
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRINOV. 23 1917.

Signed + Ldn. 8.17

Special survey held on each  
screen staff - charged

N.B.-If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

Yours truly  
J. H. RECORD. MC 8-14

N.S.P. 14  
15.11.14

J. H.  
RECORD

• THE SURVEYS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2018

Lloyd's Register  
Foundation