

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

NOV 29 1939

Date of writing Report 25/11/39 When handed in at Local Office 28/11/39 Port of Manchester

No. in Reg. Book 29058 Survey held at Manchester Date, First Survey 14/11/39 Last Survey 23/11/1939  
 on the Machinery of the ~~Wood, Iron or Steel~~ MANCHESTER REGIMENT (No. of Visits 4)

Tonnage Gross 5989 Net 3199 Vessel built at Haverston, Hill-on-Tees By whom Furness S.B. Co. Ltd. When 1922, 3 no.  
 Engines made at Middlesbrough By whom Richardsons, Westgarth & Co. Ltd When 1922  
 Nominal Horse Power 1004 Boilers, when made (Main) 1922 (Donkey)   
 No. of Main Boilers 4 SB Owners Manchester Liners Ltd Owners' Address \_\_\_\_\_  
 No. of Donkey Boilers  Managers \_\_\_\_\_ (If not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers 190 lbs/sq  Surveyed Afloat or in Dry Dock No 8 Dock Port Manchester Voyage \_\_\_\_\_  
 in Donkey Boilers  (State name of Dock.)

Last Report No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) B.S.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the date and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? \_\_\_\_\_

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? \_\_\_\_\_

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler F & C 14/11/39 S 17/11/39 P 21/11/39 Present condition of funnels Good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 190 lbs/sq

Did the Surveyor examine the Safety Valves of Donkey Boiler?  To what pressure were they afterwards adjusted under steam? \_\_\_\_\_

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? Yes and of the Donkey Boiler?

Has screw shaft now been drawn and examined?  Is it fitted with continuous liner?  Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed?  If so, state reasons \_\_\_\_\_

Has the shaft now fitted been previously used?  Has it a continuous liner?  Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft  State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft \_\_\_\_\_

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done complete

Now Done

All four boilers examined internally & externally with their safety valves & all mountings. Mountings generally overhauled as required.

Port Boiler :- 2 - C.C. screwed stays renewed

Centre Boiler :- 3 - C.C. screwed stays renewed

Star Boiler :- 2 - C.C. screwed stays renewed

Fore'd Boiler :- 1 stay tube renewed. 2 nuts on screwed stays renewed.

Safety valves on all four boilers adjusted under steam to pressure stated above.

General Observations, Opinion, and Recommendation:— This vessel's machinery as now seen is in good condition & eligible, in my opinion, to remain as now classed & to have fresh record of B.S. 11-39

Survey Fee (per Section 89)	B.S.	£ 5 : - : -	Fees applied for <u>25/11/39</u> Received by me, _____
Special Damage or Repair Fee (if any) (per Section 90.)		£ : : :	
Travelling expenses (if chargeable)		£ : : :	

J.B. Goodwin  
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE 12 DEC 1939  
Assigned 11.39

Report of Survey for Repairs, &c., of Engines and Boilers.

Faint, mostly illegible text from the original document, likely containing technical details and survey data.

*It held a few stay  
Guards*

It is submitted that  
this vessel is eligible for  
THE RECORD, 11/39

*W. J. P.*  
*W. J. P.*