

LB 14 1339

Date of writing Report 7/2 1989 When handed in at Local Office _____ 19____ Port of Rotterdam
 No. in Book. Survey held at Rotterdam Date, First Survey 20/1 '89 Last Survey 6/2 1989
7518 on the Machinery of the Wood, Iron or Steel M. V. Citrine (No. of Vols. 6)

Age	Gross	Vessel built at <u>Hardinwood</u> By whom <u>Lehigh Valley</u> When <u>1934</u>	Year.	Month.
	Net	Engines made at <u>Cologne</u> By whom <u>Lehigh Valley</u> When <u>1934</u>		
nominal	Power	Boilers, when made (Main) <u>(Donkey)</u>		
of Main Boilers		Owners <u>William R. Lehigh</u> Owners' Address <u>Glasgow</u>		
of Donkey Boilers		Managers <u>and</u> Port <u>Voyage</u>		
Pressure—		If Surveyed Afloat <u>on</u> Dry Dock <u>(State name of Dock.)</u>		
Main Boilers		Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
Donkey Boilers				

st Report No. _____ Port _____
 Particulars of Examination and Repairs (if any) Sam. T.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and ideas being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

amage cases where the Survivor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined *Yes not required.*

a damage report made by anyone else? If so, by whom? Unknown in survey

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " "

is was not done, state for what reasons? _____

what parts of the Boilers could not be thus thoroughly examined? _____

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? }

latest date of internal examination of each boiler.....✓

the Surveyor examine the Safety Valves of the Main Boiler? _____

the Surveyor examine the Safety Valves of Donkey Boiler?.....

the Surveyor examine all the manholes, doors and their fastenings of the

the Surveyor examine the drain plugs of the Main Boilers?.....

the Surveyor examine all the mountings of the Main Boilers? ✓

screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

shaft now been changed? *Yes* If so, state reasons *shaft badly grooved and bent at propeller cone*

the shaft now fitted been previously used? no Has it a continuous liner? no Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no

date of examination of Screw Shaft 27/1/29 State the distance between lignum vitæ or bearing metal of stern bush and top of after bearing of screw shaft a fit

Engine parts, when referred to by numbers, should be counted from forward.

did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

On the results trial the 19th of January 1939 the newspaper ran
but in the sternsheet.

Stern placed in drydock menshops drawn out^{est} in lathe and
 found same badly ground and bent at propeller cone, same
 now replaced by a new menshops marked 220405 No 260 L.S./P.E.W. 27/1 '89.
 Cracked sterntube removed, sternframe slightly bored out and
 a new sterntube fitted as required now satisfactorily fitted with
 new stern- and neckbrack. Alignment of shafting out^{est} and
 found good. Cylinders Nos 1 & 6 with valves & gear piston & rings, overhauled
 in harness out^{est} and found in order. Crank & thrust shaft out^{est} and found
 in order.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, R.S. 9,11, B.&M.S. 9,11, \times L.M.C. 9,11, or \times L.M.C. 140 lb., F.D., &c.)

As per first entry report forwarded herewith

roy Fee (per Section 29).....	£ : :	Fees applied for 13.2.19 39
cial Damage on Fee (if any).....	£ 75-	
(per Section 29.)		
velling expenses (if chargeable).....	£ : :	Received by me, 19

Committee's Minute _____
Assigned _____ See Rot. J.C. 27832

F. Williams
Engineer Surveyor to Lloyd's Register of Shipping.

002038-002050-0057