

7 - NOV 1947

No. 22816

REPORT OF SURVEY FOR REPAIRS, &c.

Port of Grimsey
No. in Survey held at Immingham Date, First Survey 2nd November Last Survey 3rd November 1947
eg. Book. on the Steel "EMPIRE CONLEA" (No. of Visits Two)

TONNAGE:— Built at Rendsburg By whom W. J. R. R. & Co. Ltd. When 1939
ROSS 250 Owners Jeppesen, Heaton & Co. Owners' Address 128 Addison Gardens London W.14
UNDER DK. 186 Managers ✓ (If not already recorded in Appendix to Register Book)
ET 149 Port belonging to London

veyed Afloat or in Dry Dock? Afloat Name of Dock Kings Dock Destined Voyage
LDBorDBa feet; uE & B feet; f feet
l capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys
(Including date of N.B., if any).

N.B.—All alterations in the existing records should be underlined.

st Report, No. Port

ical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

amage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Yes. Copy

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

damage report and interim certif. attached Was a damage report made by anyone else? if so, by whom? ✓

PAIRS, OR EXAMINATION AS PER RULE, FOR DAMAGE

Damage stated to have been sustained through striking S.W. corner of lock pile on 2nd November 1947 when preparing to proceed to sea from Immingham for London now done. Shell plating (S.S.) No. 1 (from forward) plates in 1st above main sheer strake and main sheer strake found indented, rivetting and caulking started. House pipe (S.S.) pushed up through deck plating and deck plating in way lifted, anchor shank bent. Internal strapping between stem plate and side plating (S.S.) started on after edge in way of indented shell plating. No. 1 (from forward) frame (S.S.) fractured and distorted. Deck beam under keel fore-castle deck plating started.

Temporary Repair:—The vessel being loaded and urgently required the following (see overleaf)

ARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items.
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place								

IT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
See rpt. <u>Good</u>	<u>✓</u>	<u>Good</u>	(State if on Felt.)
of Decks <u>See rpt. <u>Good</u></u>	Ceiling <u>✓</u>	Coal Bunkers, Openings, Covers, &c. <u>✓</u>	When fitted, Month Year
<u>Good</u>	Cement or Asphalt <u>✓</u>	Oil Bunkers	
Fastenings <u>See rpt. <u>Good</u></u>	Rudder <u>✓</u>	Scuppers <u>Good</u>	Boats <u>Good</u>
Plating <u>See rpt. <u>Good</u></u>	Steering gear and its connections <u>Good</u>	Cargo Hatchways <u>Good</u>	Masts, Yards, &c. <u>Good</u>
" In way of sidelights <u>✓</u>	Windlass <u>Good</u>	Hatches <u>✓</u>	Condition, how ascertained (State if wedges removed.)
<u>See rpt. <u>Good</u></u>	Have pumps been examined and found efficient? <u>✓</u>	Planking	Equipment letter <u>✓</u>
Frames <u>✓</u>	Have Sluice Valves been examined and found efficient? <u>✓</u>	Caulking	Anchors, No. of <u>2 (3B + 1B. See letter)</u>
nals <u>✓</u>	Have Watertight Doors been examined and found efficient? <u>✓</u>	Treenails	Cables (State if now ranged) <u>to 3.1.48</u>
es <u>✓</u>	Have Ventilators and their Coamings been examined and found efficient? <u>Good</u>	Breasthooks & Stems	" length <u>✓</u> mean diamr. <u>✓</u>
<u>✓</u>	Air and Sounding Pipes <u>✓</u>	Transoms, Pointers & Crutches	" Rule length <u>✓</u> size <u>✓</u>
tom Plating <u>✓</u>	Doubling Plates under Sounding Pipes <u>✓</u>	Timbers of Frame at openings	Chain Locker <u>✓</u>
Tanks been examined internally? <u>✓</u>		" " at other places	Hawsers & Warps <u>Good</u>
Tanks been tested? <u>✓</u>		Stringers, Clamps & Shelves	Standing and Running Rigging <u>Good</u>
		Sailings	Sails <u>✓</u>

al Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1,38."

vessel, so far as now seen, is in good and efficient condition and eligible, in my opinion, to remain as "class contemplated" (see Hull Surveyor's Report) and to permanent repairs to shell plating, anchor, deck plating etc in way of house pipe (S.S.) at first available opportunity

(per Section 29) £ : : Fees applied for, 5-11-1947
Damage Fee (if any) £ 10 : 10 : 0
Expenses (if chargeable) £ : 2 : 3
Surveyor's Fee (if any) £ 5 : 5 : 0
Day attendance fee
Tee's Minute

Received by me, 19

Surveyor to Lloyd's Register of Shipping.

002038-002050-0104

Lloyd's Register Foundation

temporary repairs have been carried out:-

Cement box fitted externally around the raised portion of the starboard house pipe on the fore-castle deck. Cement box fitted internally in way of riveted plating.

The temporary repairs were examined on completion and found satisfactory; it is however recommended that permanent repair be carried out at the first available opportunity

G. B. Sux

Edwards

the conveying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

ANCHORS.																	
Number of Certificate.	Anchors.*	WEIGHT. EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]