

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

19 AUG 1950

Date of writing Report 5/8 19 50 When handed in at Local Office 19 50 Port of Rottterdam
 No in Reg. Book. Survey held at Rottterdam Date. First Survey 29/7 Last Survey 31/7 19 50
36958 50964 on the Machinery of the Wood, Iron or Steel m.v. "ALTAIR" (No. of Visits 2)

Tonnage { Gross 6480 Vessel built at W. Harlepool By whom Wm Gray & Co Ltd Year. Month. When
 Net Engines made at Sengels, Gb. Hook By whom Yard N° 1236 When
 Nominal Horse Power { Boilers, when made (Main) (Donkey)
 Owners M. van Noordt Gaudriaan & Co's Owners' Address Storm. Maats (if not already recorded in Appendix to Register Book.)
 Managers Storm. Maats Port Rottterdam Voyage ✓
 If Surveyed Afloat or in Dry Dock Pelgrimskade (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years assumed may expire.	Machinery and Boiler Surveys (including date of N.B., if any)
<u>100A1</u> <u>(Class Contemplated)</u>		<u>aid eng. ✓</u>

Particulars of Examination and Repairs (if any) Completion Electr. Equipment.
 Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

Did the Surveyor personally go inside each Donkey Boiler separately and make a through examination at this time?

If not, state for what reasons. What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel(s).

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons. Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft. State the wear down in the stern bush.

Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. complete.

At request of the Sunderland Surveyors examined completion of the electrical installation: The following items shall with:
 Crews and Emigrants Hot water tanks, change bore placed, cables fitted.
 Emigrants Accommodation: Starboard side heaters and lights wired up, lights fixed. Port side plugs and lights connected.
 All sub-circuits connected into distribution boxes.
 Chief Steward: Room loud-speaker fitted.
 Emigrants Bar - cable ends connected to fuse box and to Refrigerating Machinery.
 Gyro Room - Batteries fitted in box and all connections fitted.
 1000 Watt-heaters, efficient isolating switches now fitted.

The Electrical Installation completely megger tested and found above Rule Requirements.

General Observations, Opinion, and Recommendation.—
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, LMC 9.11 or LMC 140 lb., FD, &c.)

The Electrical Equipment of this vessel is in my opinion in efficient condition.

Survey Fee (per Section 20) no fee charged
 Special Damage or Repair Fee (if any) £
 Travelling expenses (if chargeable) £

Fees applied for 19
 Received by me, De B. J. J. J.
 19 50

Committee's Minute FRI. 1 SEP 1950
 Assigned See minute on Hpl E.E. Rpt. 1940.

Engineer Surveyor to Lloyd's Register of Shipping.



002051-002061-0052

Insert Character of Ship and Machinery precisely as in the Register Book.

Fitting of some electrical items
now completed

It is submitted that this
vessel is eligible to remain
as **CLASSED**.

P.S.
29-8-50.

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

© 2020



Lloyd's Register
Foundation