

Rpt. 8.

(Received at London Office 24 AUG 1949)No. 129327

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report.....19..... When handed in at Local Office.....19.....

Port of LIVERPOOLNo. in  
Reg. Book.Survey held at Birkenhead.Date, First Survey 22/6/49Last Survey 6/8/19 4956271on the ~~H.V. 1000~~ Steel T.S. MV "D.L. HARPER".

TONNAGE :-

GROSS 12241UNDER DK. 11596NET 6588Built at Hamburg.By whom Deutsche Werft A.G. Bet.

YEAR.

When 1933

MONTH.

9Owners Anglo-American Oil Co. Ltd.

Owners' Address

(If not already recorded in Appendix to Register Book).

Managers Esso Transportation Co. Ltd.Port belonging to London.Surveyed Afloat or in Dry Dock? Dry dockName of Dock Bannell Lane

Destined Voyage

CeLDorDBa

feet ; uE &amp; B.

feet ; f

feet

total capacity

tons. FPT

tons ; APT

tons ; MT

feet

Particulars of Classification (which must be inserted  
precisely as in Register Book & Supplements)CHARACTER  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.Machinery and Boiler  
Surveys  
(Including date of N.B., if any).

\*100A1 9,48.

\*LMC CS 9,48.

SS.BKN. -9,48.

9,48.

DBS 9,48.

TS CL(PN) 9,46.

(S) 8,48.

Oil Engine.

Carrying petroleum in bulk.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.Last Report, No. 4146Port P. SD

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as  
painted on Ship and now verified } 8 ft 6 1/2 ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING

Vessel in dry dock, shell plating & rudder cleaned examined and coated

Generally examined decks, casings, hatchways & their closing appliances, windlass, steering gear & general equipment, all found or placed in efficient condition.

REPAIRS. WEAR & TEAR.

Windlass cylinders renewed. Two lengths cable (30 fms) renewed  
Rudder post removed, coupling faces built up where somewhat wasted, distance piece fitted, post refitted and new coupling bolts fitted.

P.T.O.

SUMMARY OF DAMAGE REPAIRS :-

Renewed ...  
Removed and Faird or Repaired  
Faird or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors and Bracket Floors

Beams.

Inner Bottom Plates.

Dk. Plates.

Other Items :-

PRESENT CONDITION OF THE

Decks

Good

Caulking of Decks

"

Coamings

"Beams & Fastenings where used

Outside Plating

efficient & "

" " In way of sidelights

not used

Frames

where used good

Reverse Frames

not used

Longitudinals

where used good

Transverses

" " "

Floors

" " "

Keelsons

" " "

Stringers

" " "

Inner Bottom Plating

not used

Have the Tanks been examined internally?

No

Have the Tanks been tested?

No

Bulkheads

where used good

Celling

none

Cement or Asphalt

not used

Rudder

good

Steering gear and its connections

"

Windlass

"

Have pumps been examined and found efficient?

No

Have Sluice Valves been examined and found efficient?

No

Have Watertight Doors been examined and found efficient?

No

Have Ventilators and their Coamings been examined and found efficient?

Yes

Air and Sounding Pipes

good

Doubling Plates under Sounding Pipes

not used

Engine Room Skylights

good

Coal Bunkers, Openings, Covers, &amp;c.

none

Oil Bunkers

not used

Scuppers

good

Cargo Hatchways

"

Hatches

"

Planking

Caulking

Treenails

Breasthooks &amp; Stemson

Transoms, Pointers &amp; Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps &amp; Shelves

Salting

State if examined.

Copper, or Y.M.

(State if on Feet.)

When fitted, Month

Year

Boats

Masts, Yards, &amp;c.

Condition, how ascertained from dk

(State if wedges removed)

Equipment letter 21Anchors, No. of 3 & 1Cables (State if now ranged) Yes" length 330 fms mean diam. 2 1/32" Rule length 330 fms size 2 1/16Chain Locker not usedHawsers & Warps sufficientStanding and Running Rigging efficientSails none

General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38." The vessel so far as now seen is in

efficient condition & eligible in my opinion to remain as classed with fresh record of survey 7,49 without condition

Endorsement B Indented shell plating (P & S) to be dealt with at Owners convenience

Survey Fee (per Section 29)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

17 AUG 1949

Received by me,

19

Kenneth C. Murray & T. R. Crosby

Surveyors to Lloyd's Register of Shipping.

LICENCE CASE.

Committee's Minute

LIVERPOOL 23 AUG 1949

Character Assigned

Y.49 BKN. Without Special Conditions(With Endorsement).D.B.S. 8.49. T.S. (P). 6.49.

002442-002448-0053

Lloyd's Register  
FoundationOIL ENGINES  
CONTINUOUS SURVEY



A number of minor repairs effected.

Alteration. Auxiliary rudders fitted to main rudder in accordance with approved drawing forwarded with London letter M of 7th July, 1949. which is returned herewith.

SPECIAL REASONS LIST. Indented plating (p.s.) not dealt with, considered efficient and may be dealt with at Owners convenience.

Bower anchor now supplied (particulars below)  
Windlass cylinders now renewed, delete from S.E. list.

Steering Trials. In accordance with Secretary's letter "M" dated 14/7/49, attended steering trials carried out by Owners in Liverpool Bay 6/8/49. Report & graphs of results forwarded to London office 15/8/49.

Vessel undocked 29/7/49

Licence No. E 3250

Items checked with specification

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
LPH BC 23378	1st Bower											95					
	2nd "														Stockless		
	3rd "	93	0	14				65	0	0	0						Cardiff 24/9/48 J. W. Dorey.
	Collective Weight																
	Stream.....																
	Kedge .....																


\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per rule.		Description.	Makers of Cables.	Where and when tested and Superintendent.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			
LPH BC 44717	Fathoms.	Ins.	Tons.	Tons.	Cwts. qrs. lbs.	Cwts. qrs. lbs.	Fathoms.	Ins.			
	30	2 1/16	125.1	175.12	107 1 3		30	2 1/16	Steel Link		Cardiff 13/6/49 J. W. Dorey.
Iron Stream Chain } or Steel Wire }											

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021

Lloyd's Register  
Foundation