





ARABIAN PRINCE

examined under steam and their safety valves adjusted.

Boiler Repairs.

A number of defective tubes removed in both boilers and a considerable number of tubes expanded. Several stay tubes re-welded to tube plate.

A number of defective C.C. wrapper stays removed.

Port boiler soot blower tube removed.

Minor repairs to mountings.

Port and starboard boilers hydraulically tested upon completion of repairs and found in good order.

Oil Fuel Conversion.

All boilers fitted to burn oil fuel, unit pumps and all relevant gear supplied by makers (Wallend) now fitted as per London approved plan and Rule Requirements. Steam smothering system fitted.

Oil burning, control gear, and fire fighting equipment tried under working conditions and found satisfactory.

Electrical Equipment

Electrical equipment examined and tested under working conditions.

Generators, switchboard, fittings, fuses and cables examined. Insulation test carried out. All found or placed in efficient condition.

Repairs

Main switchboard cleaned & overhauled. Generators generally overhauled.

All accommodation wiring and fittings overhauled, several circuits renewed and new fuse boards fitted. Navigation circuits renewed, crew quarters etc. renewed. Engine and boiler room lighting circuits overhauled and several additional points fitted. Large circuits overhauled.

Tested on completion and found satisfactory.

Seams checked.

J. H. Williams.