

Rpt. 8

Date of writing Report 25.11.59

When handed in at Local Office

30 NOV 1959

Port GRIMSBY

No. 28094

Received London

Survey held at Grimsby

No. of Visits 1

First Date and 19

Last Date 23.11.59

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B.

03455

on the Iron or Steel s.s. "BARNETT"

Tons gross 483

Built at Beverley

By Whom Cook, Welton & Gemmell Ltd.

Year 1937 Month 9

Owners Crampin Steam Fishing Co. Ltd.

Owners' address
(If not already in R.B.)

Managers

Port of Registry Grimsby

Surveyed Afloat or in Drydock on Slipway Name of Dock Fish Dock, Grimsby

Date of last examn. in Drydock 23.11.59

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 28028
To be filled in at Head Office.

Port

G.M.S.

Particulars of Classification (which must be inserted precisely as
in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
+100A1	Trawler	+LMC	7,58
D.S.	4,59	MB	9,59
S.S.	7,58	TS	CL 1,57
		SPS	7,58

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Docking Survey.

Wear and Tear Repairs:— Minor sundry repairs effected

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

Has a Survey also been held on machinery of the Ship?

Yes

Is Classification Certificate required? If so, to be sent to

No

If so, is the Report sent now, or when will it be sent?

Now

Has Interim Certificate been issued?

Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel, so far as now seen, is eligible, in my opinion to remain as Classed with fresh record of D.S. 11,59.

D.S. 11.59
J. Thompson
7/12/59A. Thompson.
Surveyor to Lloyd's Register of Shipping

Date of Committee

TUESDAY 15 DEC 1959

Minute

D.S. 11.59

T.S. 11.39

Noted
for
Heads© 2020 clean
CRSP
Lloyd's Register
Foundation

002490-002497-0037

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR.

SURVEY

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR				
Items	Now Examined	Tanks	Now Examined Internally	Now Tested
	YES NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock	Yes	F.P. Tank	Not examined	Not examined
Rudder lifted	No	A.P. "	-	-
Weather Decks, Superstructures and Casings	Yes	D.B. Tanks (indicate Oil Fuel) and Cofferdams	-	-
Hatchways, Covers, closing and securing appliances	Yes			
Ventilator coamings, skylights, companionways and closing appliances	Yes			
		Fresh Water Tanks	-	-
Holds	Not examined	Deep Tanks	-	-
		Oil Fuel Bunkers and Settling Tanks	-	-
'Tween Decks	-			
		Side Tanks	-	-
Fore Peak Spaces	-	Wing Tanks	-	-
After " "	-	Other Tanks	-	-
Engine Space	-			
Boiler "	-	Suez Canal Bunker		
Under Engines and Boilers	-			
Tunnel and Well	-			
Coal Bunkers	-	Cofferdams	-	-
Chain Locker	-			
Other Spaces	-	Pig Stock		

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held?

If so, state which.

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached.

Have any alterations to the approved scantlings and arrangements now been effected?

If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Good	Ceiling and Cargo Battens	-	Sluice Valves examined and found	-
" " in way of side scuttles	-	Cement or Asphalt	-	Air and Sounding Pipes	Above Deck Good
Rudder and Sternframe	Good	Cargo and other Hatchways	Good	Doubling Plates under Sounding Pipes	-
Decks	Good	Hatches and closing appliances	Good	Masts and Rigging examined and found	Good
Superstructures and their closing appliances	Good	Ventilators, their coamings	-	Condition, how ascertained	From Deck
Coamings and Casings	Good	and closing appliances	Good	(State if wedges removed)	-
Beams and Fastenings	Not examined	Companionways and Skylights	Good	Chain Locker	-
Frames	-	Shell Openings	-	EQUIPMENT	
Reverse Frames	-	Ash Shoots	-	Equipment Letter	-
Longitudinals	-	Overboard Discharges and Scuppers	Good	Anchors, No. of	2B. 1K Condition Good
Transverses	-	Freeing ports	Good	Cables (State if now ranged and examined)	-
Floors	-	Steering Gear (Main and Auxiliary)	-	" length	stated complete
Keelsons	-	examined and found	Good	(on board)	mean diam.
Stringers	-	Windlass examined and found	Good	" Rule Length	Size
Inner Bottom Plating	-	Pumps " " "	Good	Hawsers and Warps	Sufficient
Bulkheads and Tunnel	-	W.T. Doors " " "	-	State if any Anchors or Chain Cable have	No
				now been supplied or retested, if so,	
				complete Report 8(Eq) and attach.	

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? None

See Below

REMARKS, REPAIRS, Etc. (Contd.)