

PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Writing Report 3.7.50 19 When handed in at Local Office -5 JUL 1950 19 Port of LIVERPOOL
 Survey held at Birkenhead Date First Survey Apr 11th Last Survey June 16th 1950
 No. of Visits 26

on the Machinery of the ~~Wood, Iron or Steel~~ SS PROSPECTOR
 Gross 6205 Vessel built at Port Glasgow. By whom Lithgows Ltd. Year. Month. When 1944 1
 Net 3647 Engines made at Glasgow. By whom D. Rowan & Co. Ltd. When 1944
 Boilers, when made (Main) 1944 (Donkey) 1944
 Owners Charente S.S. Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)
 Managers T. & J. Harrison. Port Liverpool. Voyage
 Surveyed Afloat & in Dry Dock Cammell Laird & Co. (State name of Dock.)
 Gross 6205 Net 3647 Boilers 2 D. Key Boilers 1 Boilers 210 Boilers 120
 Port No. Port
 Years of Examination and Repairs (if any) Docking, T.S., Oil Conversion

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides in the body of the report, should be briefly summarised at the end of the report. State also the dates and any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. None reported.
 Report made by anyone else? If so, by whom? No
 Surveyor personally go inside each Main Boiler separately and make a through examination at this time? No

Donkey Not due. What parts of the Boilers could not be thus thoroughly examined?

Means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Present condition of funnel Good

date of internal examination of each boiler. Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No

Shaft been changed? No If so, state reasons. Has the shaft now fitted been previously used? Yes Has it a continuous liner? No

Oil retaining appliance fitted at the after end? Good fit Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? No

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

Engine parts, when referred to by numbers, should be counted from forward. Complete.

Is not complete, state what arrangements have been made for its completion and what remains to be done.

Work in Drydock: the propeller, sea valves and fastenings examined. Propeller shaft drawn and examined and found in good condition. One half of stem-bush rewooded. Main condenser tested. Minor repairs effected.

CONVERSION TO OIL BURNING. This vessel has now been converted to oil burning (from coal) in accordance with the approved plans (see also ship report). The boilers have now been fitted with Wellhead-Harden joints (both main and donkey), undersides insulated, also drip-trays fitted. New and altered pipes and fittings tested. (Continued)

Observations, Opinion, and Recommendation.— State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, &LMC 9.11 or 140 lb., FD, &c.)

The Machinery of this vessel is eligible in our opinion to remain as classified, with notation of TS(CC) 4.50. Fitted for oil fuel 150° F. 6.50.

TS 3.0.0 Fees applied for 13 JUL 1950
 Conversion Repair Fee (if any) 31.10.0 Received by me, Cur Reed
 Expenses (if chargeable) 3.0.0
 LIVERPOOL 18 JUL 1950
 H.C. Lloyd
 C.A. Bedford
 J. Dobbin
 + self
 Engineer Surveyor to Lloyd's Register of Shipping.

Assess. T.S. 4.50. Lloyd's Register Foundation

002714-002724-0200 1/2

PROSPECTOR

Hot oil system examined under hydraulic test of 440 lb/sq. in. Filling, transfer, suction & discharge lines tested.

Drums fitted under filters.

A Wallhead O.F. unit η° F. 1702 installed in engine room, with heater and two pumps (η° 205425 and 221642. 1-lb test 30.1.48), 'Comyn' Separator η° 498, an additional O.F. transfer pump η° 239481 (Eng. room), together with the necessary pipes, fittings & strainers.

A steam raising set, with hand pump provided.

Extended spindles and quick release gear installed as per rules, and tried under working conditions.

The necessary spare gear supplied.

Heating coils and observation tank fitted.

Perforated steam pipes (steam smothering) fitted under boilers, also Foamite extinguisher in each stokehold, sand & hose connections.

Bitz and ballast pipes in stokehold altered & renewed in galvanized steel.

The necessary alterations to piping carried out.

The main engines & pumping arrangements tried working.

Oil burning & fire fighting plant tried under working conditions.

C. Reed

Notes
Present in R. Room: Fitter for oil fuel 6.50.
F.P. above 150°F.
It is concluded that the funnel change has been completed but the pump should be altered to confirm this.

See L.V. Letter 20/8/50

17/8/50

02.4.20
02.2.7.20
02.2.7.20

000
3100
000

02.4.20



© 2020

Lloyd's Register Foundation

0200 2/2