

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

D.565

Port ALEXANDRIA.

14th NOVEMBER, 1953.

This is to Certify that

R.W.STONEHOUSE,

undersigned Surveyor to this Society did at the request of

W. & Co.- Lloyd's Agents, at Alexandria acting on behalf of the Association, London, and with the consent of the Owner, board the Steel Screw Steamer

"BURICA"

at Port Limon, whilst lying in drydock at Alexandria on the 14th day of October, 1953 and subsequent dates for the purpose of ascertaining the nature and extent of the damage stated to have been caused by (1) Grounding in Chittagong approaches on 28th September, 1952, and (2) "PAN OCEAN" dragging her anchor during winds of gale force on the 6th March, 1953 and contacting BURICA heavily on starboard at Alexandria.

For further details please see ship's log books.

On examination it was found:-

RECOMMENDED.

Port side.

slightly set up
corners, maximum $\frac{1}{2}$ "

Plate to be faired in place.

locally indented
depth approx. $2\frac{1}{2}$ " over
one frame space.

Plate to be faired in place.

indented between
frames after end.

Crop approx. 10 feet remove, fair and replace with welded butt and re-rivet.

Starboard side.

indented for three
frames.

To be faired in place.

indented full length
frames.

Plate to remove, fair and refit.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly carried out and it is understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any other Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Members thereof, or the Surveyors, or other Officers or Agents of the Society."

Report No.D.565

s.s. "BURICA"

RECOMMENDED.

Indented 1 frame space.	To be faired in place.
Indented 1 frame space.	To be faired in place.
Indented at after end seam for two frame spaces.	Top seam of plate E5 to be released, and plate E5 and plate above to be faired in place, and re-riveted.
Indented one frame space.	To be faired in place.

The above recommendations made so as to place
the vessel in the same good and efficient condition as before the
damages sustained.

No repairs have yet been effected to the above damages
reported, but it is estimated that they should cost approximately
£180.- for damage (1), and £180.- for damage (2) at current prevailing
rates in Alexandria exclusive of drydocking charges, which will amount
to three days.

Robert Stonehouse
.....
SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.



© 2021

Lloyd's Register
Foundation

0186 72