

Rpt. 8

Port Oslo

No. 9197

Date of writing Report 10/1/61

When handed in at Local Office 10/1/61

Received London

Survey held at Sandefjord

No. of Visits one

First Date and 19

Last Date 29/12 19 60

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

65934

X.S.S.

"JAINA"

on the Iron or Steel M.S.

Tons gross 6819

Year 1930 Month 9

Built at Newcastle

By Whom Armstrong Whitworth (S.Bs.)

When

Owners Bulls Tankrederi A/S

Owners' address (If not already in R.B.)

Managers Anders Jahre

Port of Registry Sandefjord

Surveyed Afloat or in Drydock Afloat

Name of Dock Sandefjord harbour

Date of last examn. in Drydock -

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 791

Port Oslo

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
+ 100	A1	IMC.	
	Oil Tanker	CS.	9/56
	(Dr.)	ABS.	9/56
	5/52	TS(CL)	10/55
	SS.	9/56	Sps.
	9/56		9/56
	DS.		
	9/56		

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Towing to Grimstad for breaking up.

Now Done:-

The vessel examined afloat.

All hatch covers, companionways, door openings, ventilators, superstructure and bulkheads found efficiently closed.

When examined the ship was lying at anchor. During the towing no steam will be available. For pulling the anchors, steam will be supplied from the tug boat and anchors can be dropped but not recovered. No power will be available during towing and rudder now locked in midship position. A selected number of cargo tanks generally examined and found satisfactory.

In view of the examination now made it is considered that the vessel is in a satisfactory condition to be towed to Grimstad for breaking up.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship?

No

Is Classification Certificate required? If so, to be sent to No.

If so, is the Report sent now, or when will it be sent?

-

Has Interim Certificate been issued? Yes, copy attached.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship, so far as now seen, is eligible to remain as classed without any fresh record of survey.

L. Tveit.
Surveyor to Lloyd's Register of Shipping

Date of Committee

THURSDAY 2 FEB 1961

Minute

Noted - See the minute dated 13.1.61



© 2020

Lloyd's Register Foundation

See Committee's Minute dated 13/1/61 S.L.B. 31/1/61

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Items	Now Examined	Tanks	Now Examined Internally	Now Tested
	YES NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock		F.P. Tank		
Rudder lifted		A.P. "		
Weather Decks, Superstructures and Casings		D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances				
Ventilator coamings, skylights, companionways and closing appliances		Fresh Water Tanks		
Hold		Deep Tanks		
'Tween Decks		Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces		Side Tanks		
After " "		Wing Tanks		
Engine Space		Other Tanks		
Boiler "		Cargo Tanks (Tankers)		
Under Engines and Boilers				
Tunnel and Well		Cofferdams		
Coal Bunkers		Pump Rooms		
Chain Locker				
Other Spaces				
		Have Tanks now Examined been Cleaned as Necessary?		
		Have Strains in Cargo Tanks (of Tankers) been removed?		
		Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary? _____

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? _____

Have the bilges been cleaned out and examined? _____ Has cement in bottom been examined? _____

Has steelwork had rust removed and afterwards been recoated as necessary? _____

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? _____

Has a Load Line Survey been held? _____ If so, state which _____

Have the shell and deck plating been drilled as per Rule? _____ If so, Report 8(Dr) to be attached _____

Have any alterations to the approved scantlings and arrangements now been effected? _____ If so, report details in body of Report _____

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found	
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes	
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes	
Decks	Hatches and closing appliances	Masts and Rigging examined and found	
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)	
Coamings and Casings	Companionways and Skylights	Chain Locker	
Beams and Fastenings	Shell Openings	EQUIPMENT	
Frames	Ash Shoots	Equipment Letter	
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition	
Longitudinals	Freeing ports	Cables (State if now ranged and examined)	
Transverses	Steering Gear (Main and Auxiliary) examined and found	" length mean diam. (on board)	
Floors	Windlass examined and found	" Rule Length Size	
Keelsons	Pumps " " "	Hawsers and Warps	
Stringers	W.T. Doors " " "	State if any Anchors or Chain Cable have now been supplied or retested, if so complete Report 8(Eq) and attach.	

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee Kr. 200.-

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable) Kr. 100.-

Second Surveyor's Fee (if any)

Date when A/c. Rendered

[Signature]

© 2020

Lloyd's Register Foundation
10/1/61.