

Rpt. 8

JWK.

Port of ROTTERDAM.

No. 48691  
119 JAN 1960

Date of writing Report 13-1-1960.

When handed in at Local Office

Received London

Survey held at Rotterdam

No. of Visits 3

First Date 6-1-1960.

Last Date 12-1-1960.

# REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

24678

S.S.

"ORION"

Tons gross 2034

Year 1930

Built at

Flensburg

By Whom

Flensburger Schiffs. Ges.

When

Owners

Koninkl. Nederl. Stoomb. Maats. N.V.

Owners' address  
(If not already in R.B.)

Managers

Port of Registry Amsterdam

Surveyed Afloat or in Drydock afloat

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 5069

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
100A1	ES 5-55
Classed 10-49	MBS 5-59
DS 7-59	TS 12-57 N CL
SS (Dr) 5-55	Sps. 4-55

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined to Owners, but

Freeboard as marked on ship and now verified

— ft — ins

not required

Was a damage report made by anyone else? If so, by whom?

unknown

EXAMINATION AND REPAIRS AS PER RULE FOR DAMAGE SURVEY & PERMANENT REPAIRS.

This ship was reported to have sustained damage due to collision with "Lisa Eichmann" outside the Elbe on the voyage from Hamburg to Dordrecht on the 3rd January, 1960.

Upon examination it has been found that portside sheerstrake with bulwark, deck stringer and strake below at aft end of midship deckhouse was heavily indented.

Now done:- (plates counted from forward); Portside: J.9 and J.11 (sheerstrake) cropped and part renewed and J.10 renewed (all in 2 plates).

H.9 cropped and part removed, faired and refitted.

K.11 and 12 (bulwark) renewed.

6 tweendeck shellframes renewed, 4 deckbeams cropped and part renewed, 1 deckbeam cropped, part removed, faired and refitted, 5 beamknees renewed, 1 beamknee removed, faired and refitted,

7 bulwark stanchions removed, faired and refitted.

Deck stringer angle bar renewed, bulwark top rail renewed.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed	2p - 1c	6					4 p	2 bulwark plates
Removed and Faired or Repaired	1 p						1 p	
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? no

Is Classification Certificate required? If so, to be sent to

not required

If so, is the Report sent now, or when will it be sent?

Has Interim Certificate been issued?

copy attached

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or "to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

It is submitted this ship is eligible to remain as classed without fresh record of survey, subject to all conditions at present attached to the vessel's class being dealt with as previously recommended.

M. Th. G. Steenstra  
Surveyor to Lloyd's Register of Shipping


TUESDAY -2 FEB 1960

Date of Committee

Minute

Deferred for SS (by 5.60)

Noted for Hoops



© 2020

Lloyd's Register Foundation

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR DAMAGE SURVEY & PERMANENT REPAIRS SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock			F.P. Tank		
Rudder lifted			A.P. "		
Weather Decks, Superstructures and Casings			D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances					
Ventilator coamings, skylights, companionways and closing appliances			Fresh Water Tanks		
Holds			Deep Tanks		
'Tween Decks			Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces			Side Tanks		
After " "			Wing Tanks		
Engine Space			Other Tanks		
Boiler " "			Cargo Tanks (Tankers)		
Under Engines and Boilers					
Tunnel and Well			Cofferdams		
Coal Bunkers					
Chain Locker			Pump Rooms		
Other Spaces					
			Have Tanks now Examined been Cleaned as Necessary?		
			Have Strums in Cargo Tanks (of Tankers) been removed?		
			Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary? .....

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? .....

Have the bilges been cleaned out and examined? .....

Has steelwork had rust removed and afterwards been recoated as necessary? .....

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? .....

Has a Load Line Survey been held? ..... If so, state which .....

Have the shell and deck plating been drilled as per Rule? ..... If so, Report 8(Dr) to be attached .....

Have any alterations to the approved scantlings and arrangements now been effected? ..... If so, report details in body of Report .....

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—


Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	EQUIPMENT
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary)	" length mean diam. (on board)
Floors	examined and found	" Rule Length Size
Keelsons	Windlass examined and found	Hawsers and Warps
Stringers	Pumps " " "	State if any Anchors or Chain Cable have
Inner Bottom Plating	W.T. Doors " " "	now been supplied or retested, if so,
Bulkheads and Tunnel		complete Report 8(Eq) and attach.

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? no See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee .....  
 Special Damage or Repair Fee (if any) £1. 175.-  
 Travelling Expenses (if chargeable) £. 4.-

Second Surveyor's Fee (if any) .....  
 Date when A/c. Rendered .....



© 2020

Lloyd's Register Foundation  
 18 JAN 1960