

5 JAN 1963

Ship's Name ~~SS/MSX~~ "THE PRESIDENT" Gross tons 926  
 Is there a rpt. 8? Yes Port GREENOCK Rpt. No. 27200  
 No. of visits First date Last date  
 Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)  
 Date of completing rpt. Surveyed at, if different from Port above  
 Is a rpt. 9A attached? Yes MN Nature of survey Docking for Damage  
 Survey fees Damage fee Expenses  
 S.A. fee

Propeller Good DOCKING Inlet Sea connections Good Oil gland  
 Fastenings Good Wear down of stern bush  
 Has screw/tube shaft been drawn? Date of examn. Not due  
 Has shaft been changed? Has shaft now fitted been previously used?  
 Has shaft now examined/fitted a continuous liner? Approved oil gland?

**BOILERS OPENED UP AND EXAMINED.** (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG)	MAIN
	Generally examined only Good
Air heaters	
Superheaters	
Safety valves	
Mountings, doors and fastenings	
Safety valves adjusted to { Sat Spt	
Boiler securing arrangements	
Main economisers	Exhaust gas heated economisers
Steam heated steam generators	Steam generator safety valves adjusted to
Forced circulating pumps	Funnel
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?	Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee GLASGOW - 8 JAN 1963

Minute See Rept 9A.

*W. Fisher Lee*  
Surveyor to Lloyd's Register of Shipping



Lloyd's Register  
Foundation

ALSO FOR
SFL FOR
TRO
SRL
POSTING
HEADER
CERT

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a Generators		l Generators & governors
b Exciters		
c Air coolers		m Motors
d Motors		
e Air coolers		n Switchboards & fittings
f Control gear cables, etc.		o Circuit breakers
g Insulation resistance		p Cables
h Insulating oil test		q Insulation resistance
i Overspeed governors		r Steering gear generators & motors
j Magnetic couplings		s Navigation light indicators
k Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.


Ship placed on slipway on account of DAMAGE stated to have been caused by the ship grounding at Drogheda, Ireland on the 23rd November, 1962.

The following parts were examined:- Propeller, inlet sea connections and outside fastenings, outside end of stern tube, main thrust shaft & bearings, main condenser, main engine holding down bolts, M.E. attached S.W. circ. pump, windlass, Boiler cleaned internally & generally examined as it was stated that salt water feed was used whilst ship was grounded.

Upon examination found:- M.E. attached S.W. circ. pump bucket in worn condition. Windlass, engine bottom end brasses & top end pin bushes, main pistons, clutch operating screw spindles, and both main drive gear wheels all in a worn condition.

Repairs were not completed at this time as vessel has now been sold to Messrs. Arnot, Young, Shipbreakers, Troon for scrapping and left Messrs. James Lamont & Co. Ltd.'s Yard on 13th December, 1962 under tow for Troon.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2020

Lloyd's Register  
Foundation