

9

4991

Starboard Boiler opened up
Front wall and floor refractory removed entirely, fire side of boiler thoroughly cleaned and the following defective tubes

- 3 rear wall tubes renewed.
- 6 outboard waterwall tubes renewed.
- 4 inboard waterwall tubes renewed.
- 2 - 2" screen tubes renewed.

All soot blowers overhauled and drain valves overhauled.

All repairs to port and starboard boilers effected in good order, tested out with a hydrostatic pressure of 650 lbs., found or placed in a satisfactory condition.

Both boilers tested out under working conditions.

Boiler safety valves and superheater safety valves adjusted under steam as stated above.

Oil fuel system examined and under working condition satisfactory.

Oil discharge piping found in good condition, accessible, visible, well lighted and joints

Other minor machinery repairs were done at this time.

Cert. Bl issued, copy herewith.

Notes.
Classification Survey NOT advanced.
End. 19/7/48.

