

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 12 JUL 1947)

Date of writing Report 11 July 1947 When handed in at Local Office 11 July 1947 Port of CARDIFF
 No. in Survey held at CARDIFF Date First Survey 16 June Last Survey 3 July 1947
 g. Book. (No. of Visits 8)

938 on the Machinery of the ~~WOODHOCK~~ Steel M/V "KING ALFRED"

Year. Month.

Gross 6919 Vessel built at GREENOCK. By whom GREENOCK DOCKYARD CO. LTD. When 1941
 Net 4151 Engines made at GLASGOW. By whom BARCLAY, CURLE & CO. LTD. When 1941
 Nominal - Boilers, when made (Main) - (Donkey)
 of Main Boilers - Owners KING LINE LTD. Owners' Address -
 of Donkey Boilers 2 Managers DODD, THOMSON & CO. LTD. (if not already recorded in Appendix to Register Book.)
 Steam Pressure - Port LONDON. Voyage -
 in Main Boilers -
 in Donkey Boilers 120lbs. If Surveyed ~~in~~ in Dry Dock MOUNTSTUART DRY DOCK.
 (State name of Dock.)

st Report No. Port

Particulars of Examination and Repairs (if any) Docking, Part C.S. & D.B.S.

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " " yes

not, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler S.16-6-47 P.26-6-47

Present condition of funnel(s) good

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? yes To what pressure were they afterwards adjusted under steam? 120lbs.

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers? yes

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers? yes

Has the screw shaft now been drawn and examined? yes Has it a continuous liner? yes Is an approved oil retaining appliance fitted at the after end?

Has the shaft now been changed? No. If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft 18-6-47 State the wear down in the

stern bush close Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Continuous Survey

Damage stated to have been caused by vessel grounding at Hong Kong on the 25th August 1946.

W DONE:- Vessel placed in dry dock propeller, stern bush and sea connection fastenings examined.

Propeller, shaft drawn in and examined, propeller blade tips faired and built up.

Sea cocks and valves, steering engine.

PART C.S. Examined Nos. 1 & 2 Cylinders, pistons, liners and transverse beams, Sea cocks and

valves, Steering engine, Windlass, Electrical installation examined and megger tested.

Dynamos tested under load. Governors tested.

S Examined donkey boilers internally and externally with their safety valves, doors and mountings,

Safety valves adjusted under steam to the pressure stated above.

Oil fuel installation and steam smothering arrangements examined and tested.

S.R.List Transverse beam No. 2 engine renewed.

General Observations, Opinion, and Recommendation:- The Machinery of this vessel is eligible in my

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 & LMC 9,11 or & LMC 140 lb., FD, &c.) CS 3,34,

Union to have record of LMC.CS. as contemplated and record of DBS.7,47 and notation of TS(CL) 7,47

in S.R.List concerning transverse beam No. 2 engine to be deleted.

Survey Fee (per Section 29) D.B.S. £ 7: 0: 0 Fees applied for
 Special Damage or Repair Fee (if any) £ 5: 5: 0 Received by me,
 Travelling expenses (if chargeable) £ : : 19

LICENCE CASE

FIL 15 AUG 1947

Committee's Minute

Signed

Engineer Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register
 Foundation

003429-003433-0182

003429-003433-0183

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to