

No. 134237

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

12 DEC 1951

Date of writing Report 13 Nov 1951 When handed in at Local office 13 Nov 1951 Port of LIVERPOOL

No in
g. Book Survey held at LIVERPOOL.

Date First Survey 25/8/51 Last Survey

10/10/1951
(No. of Visits 22)

0362 on the Machinery of the Wood, Iron or Steel M.V. AGAMEMNON

		Year. Month.
Gross	7829	When 1929
Net	4806	When 1929
Mineral		
Power		
Main Boilers		
Donkey Boilers		
Pressure		
Main Boilers		
Donkey Boilers		

Vessel built at Belfast By whom Workman Clarke (1928) Ltd.

Engines made at Copenhagen By whom Akt. Burmeistr & Wain,

Boilers, when made (Main) (Donkey)

Owners Ocean S.S. Co. Ltd. Owners' Address

Managers A. Holt & Co. Port Liverpool Voyage

If Surveyed Afloat or in Dry Dock Batt.

(State name of Dock) Gladstone & Bidder's Afloat.

Brocklebank D.

Report No. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Particulars of Examination and Repairs (if any) for classification.

Radical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the

of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on

ut of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides

detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and

is of any Letters respecting this case.

nage cases where the Surveyor has not made a special damage report he is required to state whether he offered his

services for this purpose, and why they were declined.

damage report made by anyone else? If so, by whom?

he Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " " Yes.

state for what reasons. What parts of the Boilers could not be thus thoroughly examined?

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? 29 Aug 1951 Present condition of funnel(s) Satisfactory

latest date of internal examination of each Boiler.

Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers? Yes To what pressure were they afterwards adjusted under steam? 100 11/15"

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Screw shaft now been drawn and examined? No Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

ft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

proved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft.

P. 5 1/2. S. 5 1/2" bush. P. 5 1/2. S. 5 1/2" in electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? Yes

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes. Please see Elec. F.E. Rep. 1/3

parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. D.B.S. complete. For classification

l items excepting those detailed below, remain to be examined.

Survey will be completed as opportunity arises.

or done:— Vessel in dry dock, propellers, sea connections & outside

fastenings examined & found in place in order.

Starbd M.E., crank, thrust, & intermediate shafting, Nos 1, 3, 6, 8, cylinders, covers, valves, pistons, rods, and top and bearings.

Port M.E., Nos 1 & 8 cylinders, covers, valves, pistons rods, and tops and bearings.

The port aft, star. fore, & star. aft, generators opened out and

examined in their entirety.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and

also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9/11, B&MS 9/11, ELMC 9/11 or

(ELMC 140 lb., FD, &c.) CS 3,34

Eligible in our opinion to remain as now noted

in the R.B. (Classification pending), with record of D.B.S. 10/51, now,

and M.B.S. cs, (with date) when the survey is completed.

P.I.O.

Fee (per Section 23) D.B.S. £ 3-0-0 Fees applied for

Alts & C.S. 28-0-0 5 DEC 1951

al Damage or Repair Fee (if any) £ 1/2 1/2 0 Received by me,

(per Section 23) £ 18 8 19

Calling expenses (if chargeable)

Committee's Minute LIVERPOOL 11 DEC 1951

Signed Deferred. At 1/3

Lloyd's Register Foundation

003467-003473-0263

Is a Certificate required? If so, to be sent to

© 2020 Lloyd's Register Foundation

Lloyd's Register Foundation

003467-003473-0263

Lloyd's Register Foundation

Main engines P&S inner & outer L.O. pumps, aux. air compressor, L.O. cocks, valves, pipes & strainers of the pumping arrangements, both main C.W. pumps, and distiller opened out and examined.

Both main air receivers, the emergency air receiver, a low pressure (130 lb) air receiver examined internally and externally together with fittings, and found in order.

The P&S oil fuel settling tanks, the oil fuel gravity tank and the port L.O. tank examined internally & found in satisfactory condition.

Donkey boiler examined internally & externally mounting doors fastenings and found or placed in good condition. Afterwards examined under steam and its valves adjusted 100 lb/D. The oil burning equipment & the fire extinguishing arrangements checked & found in order.

The main & auxiliary machinery tried under conditions with satisfactory results.

Alterations & additions.

Three of the original 5' main starting air receivers removed from vessel at this time. A manoeuvring test witnessed by the M.O.T. surveyors during which the remaining receivers proved adequate.

A new 'Allen' 5 cylinder diesel generator Serial Cyl. bore 325 $\frac{1}{2}$ x 370 $\frac{1}{2}$ stroke, now fitted.

Bedplate stamped: - K2/66041/E M.O.T. L.D. 30-3-50.

Repairs

Star. No^o 1st top and bearings re-metalled. No^o 6 lead & liner renewed.
Port exhaust gas turbo blower rotor renewed.
Both C.W. pump impellers built up where wanted.
Generator sea water and two overboard discharge valves renewed.
L.O. pump shafts built up at bearings and roller bearings renewed.
All plain tubes in donkey boiler top row renewed. (Pitted)

NOTE. Machinery particulars for classification given on attached continuation sheet.

12.01.2.6.8 to crossed blow. (piping misspelled). 8.8 ft
- 12.01.2.6.8 to crossed blow. (piping misspelled). 8.8 ft
- 12.01.2.6.8 to crossed blow. (piping misspelled). 8.8 ft



© 2020

Lloyd's Register
Foundation