

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 14 JUL 1930)

Date of writing Report 10-7-1930 When handed in at Local Office 10-7-1930 Port of BARCELONA

No. in Reg. Book. Survey held at BARCELONA Date, First Survey 2-6-30 Last Survey 4-7-1930 (No. of Visits 6)

~~Survey~~ on the Machinery of the Wood, Iron or Steel SEA "ITO TAJO"

Tonnage { Gross 3367 Net 1896 Vessel built at Bilbao By whom La Estaladura de Cast When 1917-1

Nominal Horse Power 268 Engines made at West Scotland By whom La Ma. Eng Wks. When 1917

No. of Main Boilers 283 Boilers, when made (Main) 1917 (Donkey) 1917

No. of Donkey Boilers 02 Owners La Ma. de S. de S. de S. Owners' Address La Ma. de S. de S. de S. (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 180 lbs. Managers Port Valencia Voyage

in Donkey Boilers 100 lbs. If Surveyed Afloat or in Dry Dock BARCELONA 88 (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) TS Repairs

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? See below

Do. " Donkey " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? None

Has shaft now been changed? No If so, state reasons

Has the shaft now fitted been previously used? yes Has it a continuous liner? yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 4 1/2 in

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done: Vessel placed in dry-dock and screw shaft drawn in for examination. CL. Propeller and all outside fastenings of sea connections examined and found in order.

Boiler Repairs: The back plate of the Centre Combustion Chamber in the port main boiler has been dropped and the lower portion removed. The new piece of plate is riveted at the Landings and electrically welded at the joint to the old plate. In addition to the necessary renewal of the screwed stays in way of the repair, 4 more screwed stays have been renewed. On completion of the repair, the boiler was tested by hydraulic pressure to 200 lbs/sq. and found satisfactory.

General Observations, Opinion, and Recommendation: The machinery of this vessel, as now seen is in safe working condition and eligible in my opinion to remain as classed with last record of TS CL 7,30

Survey Fee (per Section 28) TS £ 100.00 Fees applied for 12/7/1930

Special Damage or Repair Fee (if any) (per Section 28.) See below £ 50.00

Travelling expenses (if chargeable) £ 9.00

Received by me, 18.7.1930

Committee's Minute TUE. 12 AUG 1930

Assigned As now

Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 10 JUN 1932

FRI. 25 AUG 1933

TUE. 18 OCT 1932

FRI. 4 NOV 1932

FRI. 24 MAR 1933

TUE. 23 MAY 1933

FRI. 31 JUL 1931

TUE. 15 MAR 1932

TUE. 19 MAY 1931

FRI. 27 FEB '93

Insert Character of Ship and Machinery precisely as in the Register Book.

003495-003502-0045

Screw shaft examined.

Port boiler repaired.

It is submitted that
this vessel is eligible to
remain at U.L.R.D.

5730

BR
8/8/30

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation