

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

20th December 1948 When handed in at Local Office 21st December 1948 Port of BRISTOL
 Survey held at Avonmouth Date First Survey 6th October Last Survey 18th Dec. 1948
 Book No. 3451 on the Machinery of the Esso Manchester Steel screw Turbo Electric "ESSO MANCHESTER" (No. of Visits 34)
 Gross 10712 Vessel built at Chester Pa By whom Sun S.B. and Drydock Co. When 1944
 Net 6301 Engines made at Lynn Mass By whom General Electric Co. When 1944
 Nominal 1361 Bauders when made 1944 (Donkey) In this vessel the machinery engine test 110
 of Main Boilers 2 Owners Anglo-American Oil Co., Ltd. Owners' Address -
 of Donkey Boilers Managers Esso Transportation Co. Ltd. Port London Voyage -
 Main Boilers 500 If Surveyed Afloat or in Dry Dock Both
 Donkey Boilers - (State name of Dock)
 Report No. - Port -

Particulars of Examination and Repairs (if any) LMC and Classification

Surveys when held, must be reported in detail and succinctly in the terms of the rules. State clearly the cause of Repairs, if any, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be clearly separated from Repairs due to other causes), and besides being detailed in the body of the report, should be briefly mentioned at the end of the report. State also the dates and initials of any letters respecting this case.

case where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

a few words about the survey for Avonmouth -

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

Surveyor examined the following parts of each Boiler to determine their efficiency and to ascertain what parts of the Boilers could not be thus thoroughly examined?

Surveyor examined the following parts of each Boiler to assure himself of the thorough efficiency of those parts of each Boiler? Stbd boiler 8-10-48 Port 10-11-48 Present condition of funnel

Surveyor examined the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 1500 lbs/sq.in

Surveyor examined the Safety Valves of the Donkey Boilers? yes To what pressure were they afterwards adjusted under steam? Spt. 464 lbs/sq.in

Surveyor examined all the manholes, doors and their fastenings of the Main Boilers? yes And of the Donkey Boilers?

Surveyor examined the drain plugs of the Main Boilers? yes And of the Donkey Boilers?

Surveyor examined all the mountings of the Main Boilers? yes And of the Donkey Boilers?

Screw shaft now been drawn and examined? no Has it a continuous liner? yes Is an approved oil retaining appliance fitted at the after end? no

If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner? no

Approved oil retaining appliance fitted at the after end? - State date of examination of Screw Shaft - State the wear down in the bush 7/32" at outer end. If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Done. Vessel placed in drydock. Propeller and all outside fastenings examined. Propeller

Cut off and cone end of tail shaft examined.

All ship side

box gratings removed, boxes scaled and coated and gratings resecured

Main turbine rotor and stator casings and blading (rotor lifted) shafting and bearings, generator, propulsion motor, shafting and bearings, intermediate and thrust shafting and

wings opened out and examined.

Auxiliary turbo generator rotor and stator casings, blading, shafting and bearings, gears,

rotors opened out and examined. Main feed pump impellers and turbines, aux., feed pump, main and

circulating pumps, bilge, ballast, fire and sanitary pumps, oil fuel transfer pumps, lub., oil

ice pumps, main and aux., condensate pumps opened out and working parts examined. Main and aux.,

tenders examined and tested. Combustion control and service compressors examined. Air receiver

lined internally. P.T.O.

General Observations, Opinion, and Recommendation: The machinery and boilers of this vessel are in good

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 or XLMC 9,11 or 140 lb., FD, &c.)

CG 8,34, efficient condition and eligible in my opinion to have the notation of LMC 12-48 and with

ord of 2 W.T.B 500 lbs (Spt 464 lbs) HS. 11552. FD. 1361 M.N. made in the Register Book.

Survey Fee (per Section 29) £ INCLUSIVE

cial Damage or Repair Fee (if any) £ FEE

elling expenses (if chargeable) £

mmitee's Minute 4 FEB 1949

signed

4 FEB 1949

ee minute or the machy of

005534-005540-0081

W.H. Fletcher J.W. Wickell
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

005534-005540-0081

"ESSO MANCHESTER"

Valves, cocks, pipes and strainers of the pumping arrangements examined.

Both main boilers opened out and examined internally and externally together with superheater mountings and fittings. Both boilers tested hydrostatically at 450 lbs (W.P) and found tight. Drum safety valves of both boilers adjusted to 500 lbs/sq.in and superheater valves 464 lbs/sq.in and boilers examined under steam.

Oil fuel pumps examined and all valves, tanks, pipes and deck control gear of this oil fuel installation examined.

Fire fighting appliances examined. Steam smothering supplied only to the bottom of the boiler casing underneath furnace with separate control valve to each boiler in the stokehold and master control valve.

(Refugees and hold spaces) Cargo tanks and cofferdam steam smothering control valve at freeboard deck. The Lux system V-SI 28 V-SI

1.0 ~~Refugee~~ fire fighting equipment is fitted in the following positions: Stokehold after bulkhead over engine room, after engine room, behind switchboard and control panel, and over main propulsion motor. Automatic controls in alleyway on freeboard deck. CO₂ batteries now weighed and proved full.

In addition portable CO₂ plant in stokehold and a number of hand foamite fire extinguishers of various sizes are placed in all compartments, and water hose connections provided on fire pump lines in all compartments.

Repairs now done.

Main circulating pump impeller and shaft renewed.

- Ingersoll-Rand feed pump turbine casing faces built up where scored between stages.
- Main condenser - 14 tubes renewed. Condenser tested.
- Main motor air cooler - 1 tube renewed. Cooler tested.
- Port boiler - 6 generator tubes cut out and renewed 1½ diam. Found sagged slightly otherwise in order.
- Stbd. boiler/generator tube renewed; split at end in bell mouth.
- A number of other repairs and adjustments made.

The M.N. has been calculated on a working pressure of 450 lbs/sq.in. 6000 S.H.P a

conditions in wet dock and all found satisfactory. The ship was certified as being fit for service.

Electrical Equipment The electrical, auxiliary machinery was seen under working conditions and found satisfactory.

C.T.9

"ESSO MANCHESTER"

Electrical Installation: - Now Done: Electrical classification survey carried out and recommended repairs and alterations complete.

Repairs:

Main Alternator: - A new alternator rotor serial No S.E.R. 819746, S.P.F.C. 3209053 A.B. 439 H.T. 11/8/48 has been installed in place of the original rotor which was removed and fitted in the "ESSO LONDON".

The alternator was tested under working conditions after the contractor representatives had checked the balance of the rotor at all speeds both unexcited and excited and all found satisfactory. After the test under working conditions, the rotor insulation test was found to be "infinity".

Stator coil connections: - A sheet iron cover has been fitted to give mechanical protection.

Main Circulating Pump Motor Slot wedges renewed; stator winding phase to phase resistance tests made; Motor bearings renewed. Cargo and Stripping pump motors which had been immersed in salt water have been "dried out" and insulation tests are now satisfactory.

Navigation Lights: - An alternator supply has now been provided in accordance with Rule requirements.

Insulation resistance tests have been carried out on all equipment and circuits and those found below Rule requirements have been rectified.

Classification Requirements: - Lighting fittings in the centre castle tween deck space have been replaced by certified flame proof fittings and the switches controlling these lights located on the deck above. Socket outlets were removed from this space and also on the Foremast in way of vapour outlets. Forward Pump room switch removed.

The installation has been tested under working conditions after repair and found satisfactory.

Reports 13 and 4 d are in the course of preparation.

J.H. Tuckell