

No. 17694

# PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

5 APR 1951

of writing Report 5<sup>th</sup> March 1951 When handed in at Local Office

19

Port of Amsterdam

Survey held at Amsterdam Date First Survey 21-12-50 Last Survey 20<sup>th</sup> Feb 1951  
(No. of Visits 18)

on the Machinery of the Wood, Iron or Steel % " VEST "

Gross	5135
Net	3160
al	476
wer	
in Boilers	3
key Boilers	
ssure—	
Boilers	180%

Vessel built at Sunderland By whom Bartram & Sons Ltd When 1920 12  
Engines made at 1 By whom J. Dickenson & Sons Ltd When 1920 12  
Boilers, when made (Main) 1920 (Donkey)  
Owners P. H. Helgås Owners' Address  
(if not already recorded in Appendix to Register Book.)  
Managers R. J. Langfeldt Jr. Port Christiansand Voyage  
# Surveyed Afloat in Dry Dock A.D.M. (State name of Dock.)

Year Month

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements.)

CHARACTER. For Special Survey, Date of last Survey and of Periodical Surveys.	Years assured now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
+ 100 A 1		+ LMC. 8.46
Oil 8.50		B.S. 6.49
S.S. Ant. 8.46 [b]		TS.C.L. 3.49

Donkey boiler  
to be used.

Port

LMC

## Lars of Examination and Repairs (if any)

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides listed in the body of the report, should be briefly summarised at the end of the report. State also the dates and any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

age report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

REMOVED FROM BOARD.

for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

ial means, in the absence of internal examination, were adopted by the  
r to assure himself of the thorough efficiency of those parts of each Boiler?

st date of internal examination of each boiler 22/12 Starb. &amp; Centre.

4/1 Port.

Present condition of funnel(s)

good

Surveyor examine the Safety Valves of the Main Boilers?

Yes

To what pressure were they afterwards adjusted under steam?

100 lb

Surveyor examine the Safety Valves of the Donkey Boilers?

✓

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers?

✓

, and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Screw shaft now been drawn and examined? Yes

His it a continuous liner?

Yes

Is an approved oil retaining appliance fitted at the after end? no

now been changed? no

If so, state reasons

✓

Has the shaft now fitted been previously used?

✓

Has it a continuous liner?

removed oil retaining appliance fitted at the after end?

✓

State date of examination of Screw Shaft 3-1-51

State the wear down in the

Bush 4 mm Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

yes

Engine parts, when referred to by numbers, should be counted from forward.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done Special Survey complete.

placed in dry dock; tail shaft drawn, examined and found in good condition.  
cast iron propeller in order; stated some corrosion at blade tips and found 2 small pieces  
led out from the non leading edge of one blade, this being in my opinion of no consequence for the present.  
stem tube, stern bush with lignum vitae and stern gland in good condition.  
connections opened out, examined and found in order.

**ENGINE:** Crankshaft checked before dismantling; found readings not satisfactory.  
engine entirely opened out, all parts as cylinders with cyl. covers and pistons, HP poppet valves  
valve clearances & valve gear, MP & LP slide valves & clearances, crossheads with top end braces and guides  
slip shoes, connecting rods, link motion gear, crankshaft (being lifted) with crankpin bearings and  
bearings and eccentric sleeves & straps, reversing engine, and ME driven air pump, main circulating pump,  
both bilge pump examined and found in efficient condition.  
following repairs were carried out:

PLEASE SEE CONTINUATION SHEET

## General Observations, Opinion, and Recommendation.—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11, LMC 9.11 or LMC 140 lb., FD, &c.)

CS 3.34

machinery being in a good condition I am of opinion that same is eligible to remain as  
ed with fresh record of **LMC. 2.51** with notation of Tailshaft seen 1.51.

items "Donkey boiler" and "centre B astern furnace" to be expunged from Spec. R. list.

Fee (per Section 29)

£. 670.-

Fees applied for

3/1-3 1951

ATTENDANCE

£. 36.-

{

Damage or Repair Fee (if any)  
(per Section 29.)

£. 17.50

{

ing expenses (if chargeable)

19

{

Committee's Minute

THURS 3 MAY 1951

{

ned

Dee Lynn

24529

Engineer Surveyor to Lloyd's Register of Shipping



003605-003610-01471

Insert Character of Ship and Machinery precisely as in the Register Book.

Owner's address

Is a Certificate required? If so, to be sent to

Yes

Machinery of the S/S "VEST"MAIN ENGINE (repairs carried out):

LP slide valve rod renewed, LP astern guide & guide shoe (being cracked) renewed, all 3 crankpin bearings re-metalled, all main bearings (lower & upper halves) re-metalled, N°1 lower main bearing half (being cracked) renewed, piston rod of main circulating pump shinned & re-bushed, A/f bilge pumps ram renewed.

Crankshaft afterwards clockgauged; found readings now satisfactory.

Main thrust block opened out, examined and found with thrust shaft and horse shoes in good condition.

Tunnelshafting examined and found with bearings in good condition.

Alignment of straight shafting verified and found satisfactory.

SUNDRIES:

All auxiliaries, as listed below, opened out, all parts examined and found or brought in efficient condition.

Forward Weir's feed pump (water piston renewed) - A/f Weir's feed pump (water cylinder liner renewed, piston rod shinned & re-bushed) - Ballast pump (Duplex) - Sanitary pump (Duplex horizontal) replaced by a new pump of similar type & size - Both general service pumps (Duplex) - both Dynamos engines (cylinders & slide valve cleats bored out and pistons & slide valves renewed, crankshafts entirely shinned in lathe and all bearings re-metalled).

Main condenser (5 tubes renewed) and Auxiliary condenser (450 tubes renewed) hyd. tested, examined and found in good condition.

Evaporator opened out, casing & coils examined and found in order.

Feedwater heater removed from board and replaced by a new 2 stage feed heater, supplied with Certif. N° 2048. Oslo, 20-12-50.

All valves & pipes of Bilge- and Ballast-pumping arrangement examined and found or brought in efficient condition; sundry minor repairs carried out

Spare gear examined and found complete.

Engine telegraph overhauled, tried and found in order.

ELECTRICAL EQUIPMENT: Installation throughout examined and overhauled.

Both dynamos overhauled in workshop, collectors shinned & brushes renewed.

Main switchboard renewed and fitted in accordance with approved plan.

Several sub. boards renewed and an additional new sub-board for nautical instruments fitted in chart-room, fed from main switchboard by feeder cables  $2 \times 1 \times 16 \text{ mm}^2$  O.R.L.K.

Feeder cables for wireless station and for navigation lights renewed.

All cables, fittings & switches renewed in fore-ship, in wheelhouse & chartroom, in stokehold and in shaft tunnel. Further cables etc. repaired or renewed where necessary.

NEWLY FITTED (all being connected to new sub-board in chart-room):

1) Radar Installation - Decca Marine Radar - type 159 A

2) Echo Sounding Device - Hughes. MS.21 - type B.

3) Gyro Compass. - Sperry Minor - MK. E VIII.

Installation on completion of repairs tried under working condition and megger tested with satisfactory results.

4) Degaussing switchboard and cable arrangement are left in place but disconnected from the upright dynamo.

Machinery of the 5/5 "VEST"BOILERS:

All 3 main boilers (insulation stripped) examined internally and externally and found or brought in efficient condition. Sighted some slight grooves in lower part of fore front plate flange (in all 3 boilers), this being in my opinion of no consequence for the present however.

Port furnace of Starboard boiler, and Starb. furnace of Centre boiler, being deformed, jacked up and provided with half-circumferential reinforcement plates ( $4'' \times \frac{3}{4}''$ ) on the upper-half of N° 3-5-7 corrugations, fitted by E.W.

Collision clocks of Centre boiler (being wasted) renewed.

All superheater elements transported to workshop, hyd. tested, examined and found in order.

All mountings & safety valves transported to workshop, opened out, examined and found or made in order; all their fixation studs to the boilers were renewed.


Entire new boiler insulation has been fitted.

Steel steampipes transported to workshop, hyd. tested, examined and found in good condition.

Boilers afterwards tried under steam and their safety valves adjusted.

NOTE: The Stanley boiler (Scotch - 2 plain furnaces) has definitely been removed from board.

On completion of the survey the machinery has been tried under steam and found working satisfactorily.




© 2020

Lloyd's Register  
Foundation