

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 4 DEC 1936)

Writing Report 30th Nov 36 When handed in at Local Office 30/11/36 Port of NEWCASTLE-ON-TYNE

Survey held at North Shields Date, First Survey 12 Nov Last Survey 24 Nov 1936 (No. of Visits 8)

on the Machinery of the Wood, Iron or Steel ACAYUS

Gross 8010 Vessel built at Belfast By whom Workman Clark (1928) Ltd When 1935-1

Net 4752 Engines made at Newcastle By whom Hawthorn Leslie Cold When 1935

al 502 Boilers, when made (Main) (Donkey) 1935

ain Boilers Owners Anglo Saxon Petroleum Cold Owners' Address (if not already recorded in Appendix to Register Book.)

Donkey Boilers 2 Managers Port London Voyage

essure Boilers If Surveyed Afloat or in Dry Dock yes. Smiths Dock. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

ey Boilers 180 Report No. Port

Particulars of Examination and Repairs (if any) + L.M.C. - CS.

Survey, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

Cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " Donkey " " Donkey " " Donkey " "

not done, state for what reasons? Donkey boilers not yet due for survey

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Date of internal examination of each boiler

Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Shaft has been changed? If so, state reasons

Shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If not complete, state what arrangements have been made for its completion and what remains to be done

Remarks: Propeller, outside fastenings of sea connections, sea cocks and valves (opened and examined and found in good order.

Cylinders opened up, cylinders, liners, heads, pistons & piston rods examined & found in good order.

1, 3, 5 & 8 main bearing trusses & journals not Bottom end trusses & pin examined & found in good order.

Driven - Aux Air compressor (p.s. fwd), centrifugal jacket cooling water, main & piston cooling water and standby jacket cooling water pumps all completely out, examined & found in good order. Coolers for Air compressor (Aux) & examined, tested & found in order.

All pistons removed from rods, piston rod flanges machined and eight pistons of modified design fitted

Observations, Opinion, and Recommendation:— The machinery of this vessel

what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

ration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, & L.M.C. 9, 11, or 140 lb., F.D., &c.)

my opinion eligible to remain as classed and to have record C-CS with date when the survey is completed

Survey Fee (per Section 29) £ 5 : 5 : 0

Special Damage or Repair Fee (if any) £ :

Travelling expenses (if chargeable) £ :

Committee's Minute

Assigned

Survey Fee (per Section 29) £ 5 : 5 : 0

Special Damage or Repair Fee (if any) £ :

Travelling expenses (if chargeable) £ :

Committee's Minute

Assigned

Survey Fee (per Section 29) £ 5 : 5 : 0

Special Damage or Repair Fee (if any) £ :

Travelling expenses (if chargeable) £ :

Committee's Minute

Assigned

S/S "Acaus"

These new pistons (2 of which are steel) are made with increased diameter tap bolts connecting piston to piston rod, adjacent to the flange of the piston cooling water connection, in lieu of the studs. Slight corrosion of piston rod flanges had been noted adjacent to the piston cooling water connection through the securing studs becoming slightly slack.

marks from new pistons

LLOYDS. Nos. 6104, 6105, WT. 700lbs. AW. 12.11.36

" Nos. 6106, 6107, WT 700lbs AW 12.11.36

" Nos. 6108, 6109, WT 700lbs. AW. 13.11.36

" Nos. 1843, 1845 (Steel) HPB. 22-1/36

Impeller shaft for centrifugal jacket cooling water pump renewed in Stalbrit steel (worn at impeller)

several minor repairs and adjustments carried out.

Two piston rods in ANCYLUS marked 15200 KH. 2.3.24 H.C.F. 7.6.36

have had the flanges machined and have now been placed on board this vessel as spare.

js.

Advanced.
all pistons removed on account
of leakage at piston rod changed

It is not known that
this vessel is still to
remain at the Island.

SA
157.2736



© 2021

Lloyd's Register
Foundation