

Rpt. 9.

No. 9818.

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

21 SEP 1953

Date of writing Report 12-9-53 When handed in at Local Office 14-9-53 Port of SIMAPORE

No in Reg. Book Survey held at Singapore

Date First Survey 18-9-53 Last Survey 8-9-53

(No. of Visits 14)

277. on the Machinery of the Wood, Iron or Steel M.V. "NASSAU"

Tonnage	Gross 659	Vessel built at. Weymouth	By whom. Oldenbach S.B. Co	When 1944
Net	309	Engines made at. -	By whom. Clark Bros.	When 1944
Nominal Horse Power		Boilers, when made (Main) ✓	(Donkey)	
No. of Main Boilers	✓	Owners. Red Head Guncra Petroleum meats	Owners' Address	
No. of Donkey Boilers	✓	Managers.	(If not already recorded in Appendix to Register Book.)	
Steam Pressure in Main Boilers	✓	S Surveyed Afloat AND in Dry Dock No 1 D.D. Keppele	Port The Hague Voyage.	
in Donkey Boilers	✓	(State name of Dock.)		

Last Report No. Port

## Particulars of Examination and Repairs (if any) CLASSIFICATION.

Periodical Surveys, when held, must be reported in detail and briefly in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Commissions and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and, besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and details of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Is a damage report made by anyone else? If so, by whom?

1 the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey "

"

"

"

"

ot, state for what reasons. What parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the latest date of internal examination of each boiler.

the Surveyor examining the Safety Valves of the Main Boilers?

the Surveyor examining the Safety Valves of the Donkey Boilers?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

the Surveyor examine all the mountings of the Main Boilers?

the screw shafts now been drawn and examined? Yes. Has it a continuous liner? Yes. Is an approved oil retaining appliance fitted at the after end? No.

shaft now been changed? No. If so, state reasons.

approved oil retaining appliance fitted at the after end? ✓

in bush Ø 1/2" - 5 1/2" Is electric light and/or power fitted? Yes.

State date of examination of Screw Shaft. 19-8-53. State the wear down in the

insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

o parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

following remains to be done:

out 60 kw Diesel Generators Prime mover to examine in its entirety

I.E. attached as Compressor, F.W. + S.W. Cooling Pumps to examine

imping arrangements of the Independent Forward Bulge Pump to be

ried under working conditions

the extinguishing arrangements to be in accordance with Rule

agreement.

Stand By Lub. Oil Pump to install or alternative arrangement

base Gear to be checked & placed in accordance with requirement

this type vessel.

ON DONE - Vessel placed in dry dock - propellers, tailshafts drawn

C.L., stem tube & frame bushes & exhaust fastenings examined.

al Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9, II, B&MS 9, II, LIMC 9, II or LMIC 140 lb, FD, &c.)

OS 234

The machinery of this vessel, so far as now seen, is eligible in

of opinion to be classed LMC (with date) and TS CL assigned

the survey has been completed

Fee (per Section 23). £ : :

Damage or Repair Fee (if any) £ : :

(per Section 23.)

ng expenses (if chargeable) £ : :

Fees applied for

10

Received by me,

19

R. J. Dunn 2021  
Engineer Surveyor to Lloyd's Register of Shipping.

tee's Minute TUESDAY 23 SEP 1953

to be ed

Deferred

21 SEP 1953

15/9/53

on the

**"NASSAU"**

Injection valves & locks opened, examined & placed in good order.

Main & Auxiliary machinery opened & examined.

together with M.E. attached Scavenging Pumps

M.E. Thrust (roller bearing type) incorporated in main eng  
bearing opened & examined

The following Aux. units opened, examined and particulars noted :-

Starbd 60kW 6-cyl Diesel Generator prime mover.

Independent 2-stage Air compressor unit including  
Forward Hold Bulge Pump.

Independent Bulge Pump (reciprocating)

G.S. Pump & Fire Pump.

O.F. Transfer and Lub. Oil Transfer Pumps

Air receivers examined externally - shell thickness  
and capacity ascertained. Subsequently hydro tested &  
tested to 600 lbs/ft<sup>2</sup>.

Steering Gear (left type electric drive) examined  
new 2½" flexible wires fitted (6 x 24 strands) - limit  
stops adjusted & examined and tested under working  
conditions - 13 secs hard port to starboard.

Windlass (electric drive) opened, examined & tested

The pumping arrangements examined and found  
in accordance with particulars stated in 1<sup>st</sup> entry.

Subsequently tested under working conditions with  
exception of Forward Independent Bulge Pump. It was  
ascertained however that this pump is working satisfactorily  
but it requires to be examined under working conditions.

Both Main Engines started 12 consecutive times via Air  
Receivers without replenishing & capacity of receiver  
found to easily exceed requirements.

Electrical Survey carried out - insulation examined  
& on completion of repairs, megger tested & insulation  
found satisfactory - Electrical Test Entry attached.

An Independent starter has been installed and the  
motive power of the O.F. Transfer Pump can now be  
controlled from the deck.

With regard to the items stated in the Society's letter of  
the 17<sup>th</sup> July 1953 to the Owners representative the follow-  
ing is submitted for consideration

(4) "Means be provided for the initial charging of the  
starting air receivers as required by the rules"

Each Diesel Generator has its own set of batteries  
for starting and it is submitted this is an equivalent  
method for initial charging.

(5) "In the absence of a Stand By L.O. Pump - cross  
connection should be made in the lub oil system etc."

It is the Owners intention to supply and fit a new  
Stand-By lub. oil Pump on arrival at Sydney.

R.J.O



© 2021  
Lloyd's Register  
Foundation