

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report 29-6-1950.

1950.

When handed in at Local Office 30-6-1950.

1950.

Port of

SWANSEA.

11 JUL 1950

No in Reg. Book. Survey held at Swansea.

Date.

First Survey 26-6-50.

Last Survey 27-6-1950.

(No. of Visits two.)

40357. on the Machinery of the Wood-Iron or Steel t.s.m.t. "SAN PEDRO".

Tonnage { Gross 10781.
Net 6545.
Nominal Horse Power 1165.

Vessel built at Kiel.

By whom Frd. Krupp Germaniawft A.G.

Year. Month.

When 1938. 1.

Engines made at Kiel.

By whom Frd. Krupp Germaniawft AG. When 1938.

Boilers, when made (Main)

(Donkey) 1938.

Owners. Empresa Maritima de Transportes SA.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Panama.

Voyage

No. of Main Boilers -
No. of Donkey Boilers 4 DB.
Steam Pressure in Main Boilers -

Managers

If Surveyed Afloat or in Dry Dock Palmar Dry Dock.

(State name of Dock.)

in Donkey Boilers 200 lbs. (2DB)

Last Report No. 100 lbs. (2DB) Port

Particulars of Examination and Repairs (if any)

DOCKING.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

If not, state for what reasons.

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

No.

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?

If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Complete.

Now done. Vessel placed in dry dock. Propellers and all outside fastenings examined.

At the request of the Superintendent sea cocks and valves in Engine Room examined and found in good order.

General Observations, Opinion, and Recommendation.—

The Machinery of this vessel is eligible in my

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or 140 lb., FD, &c.)

opinion to remain as classed without fresh record of survey.

Survey Fee (per Section 20)

£ - - -

Fees applied for

30-6-1950.

Special Damage or Repair Fee (if any)

£ 2 - - -

Received by me,

(per Section 20.)

£ - - -

19

Travelling expenses (if chargeable)

£ - - -

Committee's Minute

1.8.50

Assigned

Deferred for comp DBS

Engineer Surveyor to Lloyd's Register of Shipping.

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register
Foundation