

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

15 DEC 1948

11 DEC 1948

Port of NEWCASTLE-on-TYNE

Date of writing Report.....19..... When handed in at Local Office.....19.....

Survey held at South Shields & Hebburn-on-Tyne Date First Survey 6-8-48 Last Survey 9-11-1948 (No. of Visits 45)

on the Machinery of the ~~Wood, Iron~~ Steel S.S. "AMERSHAM"Gross 5536 Vessel built at South Shields By whom J. Readhead & Sons Ltd. When 1941
Net 2228 Engines made at South Shields By whom J. Readhead & Sons Ltd. When 1941
Final Power 435 Boilers, when made (Main) 1941 (Donkey) -Main Boilers 2 SB. Owners Thompson Steam Shipping Co. Ltd. Owners' Address (If not already recorded in Appendix to Register Book.)
Donkey Boilers - Managers Port LONDON Voyage
Pressure 220 LBS. If Surveyed Afloat or in Dry Dock Bath. Messrs Bigham & Co. Ltd.
Main Boilers 220 LBS. (State name of Dock.) Dry Dock Messrs R.W. Hawthorne & Co. Ltd.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. Port T.S. O.F. CONVERSION
ulars of Examination and Repairs (if any) +LMC. SUPERHEAT CONVERSION.

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly stated at the end of the report. State also the dates and initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes.

Donkey " " " "

State for what reasons? What parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Test date of internal examination of each boiler Port 29.9.48. Start 4.10.48.

Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 220 LBS/0"

Surveyor examine the Safety Valves of the Donkey Boilers? yes To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes, and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? yes, and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? yes, and of the Donkey Boilers?

Screw shaft now been drawn and examined? yes Has it a continuous liner? yes Is an approved oil retaining appliance fitted at the after end? No.

Shaft now been changed? No If so, state reasons Has the shaft now fitted been previously used? yes Has it a continuous liner? yes

Approved oil retaining appliance fitted at the after end? yes State date of examination of Screw Shaft 21.10.48 State the wear down in the bush 9/64"

Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes.

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Vessel placed in drydock, propeller tailshaft, stern bush sea connections (opened out to and discharges) and outside fastenings examined and found a placed in good order. Wear down 9/64".

Main engine cylinders, covers, pistons, slide valves & chests, rods, heads top and bottom end brasses, crank, thrust and intermediate shafts and bearings, holding bolts, attached air, feed and bilge pumps, independent circulating pump and engine, ballast pumps, service pumps, main and auxiliary independent feed pumps, main and auxiliary condensers, pumping arrangements, steering engine, windlass, fan engine, dynamo engines, main auxiliary steam pipes (tested). Both main boilers examined throughout with mountings, holes, doors and fastenings and found a placed in safe working condition. Boilers examined under steam and safety valves adjusted to pressure stated above. Accumulation pressure test carried out.

O.F. Conversion.

The vessel has been converted to oil fuel burning at this time, in accordance with Secretary's letter, approved plans and Rule Requirements. The suction and pressure lines and (see continuation sheet) 273.

General Observations, Opinion, and Recommendation:— The machinery of this vessel as now seen,

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, &MS 9,11 or LMC 140 lb., FD, &c.) CS 2,34,

in efficient condition and eligible in our opinion to remain as classed with fresh

ords of T.S. (CL) 10,48: +LMC 11,48 and notation, "Fitted for Oil Fuel, 11,48 Flush

at above 150° F.; also (Spt).

Fees applied for

T.S. 3 : 0 : 0

LMC. 28 : 0 : 0

ELECT. LMC. 5 : 0 : 0

O.F. CONVERSION. 10 : 10 : 0

Received by me, 19

FRI. 21 JAN 1949

+LMC 11,48

5.10.48 Fitted for oil fuel 11,48 FP above 150°F.

CERTIFICATE WRITTEN.

005020-005028-0218 1/3

Lloyd's Register Foundation

Is a Certificate required? If so, to be sent to

S.S. "AMERSHAM"

heating coils hydraulically tested after jointing as per Rule Requirements. The installation and deck control gear in connection with the O.F. and Steam Smothering installations examined and tested under working conditions and all found satisfactory.

Particulars of the installation are as follows:-

Wallsend Howden System. N° O.B. 9865.

O.F. Transfer Pump G. & J. Weirs N° 206719. Size 6" x 5 1/2" x 15". 2 O.F. Pressure Pumps. G. & J. Weirs N° 208992 & N° 22095. (Lloyd's Test 400 lbs 14.5.47; 26.1.48.) { 2 DISCHARGE STRAINERS
2 O.F. Heaters N° 17617-8 (Newcastle Certificate N° C 27638). Pneumercator system of sounding with distance thermometers and sounding pipes in O.F. bunkers and settling tanks.

Superheat Conversion

The boilers have been fitted at this time with superheaters for supplying superheated steam to the main engines, main circulating pump engine, dynamo engines, steering engine and fan engine in accordance with the Secretary's letters approved plans and Rule Requirements. The superheater headers and elements, (NESH 1076 Newcastle Certificate N° C 27415), cast steel valves and fittings, were supplied by The North Eastern Marine Engineering Co., Ltd., Wallsend-on-Tyne and manufactured, examined and tested in accordance with the Rule Requirements. The open hearth steel seamers pipes used for the steam pipe line alterations have been fitted with steel flanges secured by screwing the pipe and flange with a vanishing screw thread and the pipes expanded into the flanges as per Rule Requirements, and on completion the pipes have been hydraulically tested in accordance with the Rules. On completion of the alterations the superheat installation was examined under working conditions and found satisfactory.

Particulars of the superheat installation are as follows:- N° S.H. 1076.

Type of Superheater: North Eastern Smoke tube. Tube manufacturers: Messrs Tubes Ltd.

Header Manufacturers: Messrs Appleby Frodingham Steel Co. Number of Elements (Total) 126.

Material of Tubes: Solid drawn steel. Internal dia. & thickness: 17 mm x 2 1/2 mm THK.

N° & Material of Headers: 8 Forged Steel 26/30 TONS. U.T.S. Thickness of Headers: 7/8".

Can the superheater be shut off and Boiler worked separately... Yes.

Is a safety valve fitted to every part of Superheater which can be shut off from boiler: Yes.

Area of Safety valve:- 3.1416 sq. Safety valves fitted with easing gear and adjusted to 220 lbs/sq. Tubes hydraulically tested to 1500 lbs/sq and headers to 660 lbs/sq.

Drain cocks fitted to free superheaters from water when necessary.

Total Superheater Surface:- 2180 sq.

Repairs:- Tail shaft key renewed (slack in keyway). Sea connections overhauled.

Main Engine:- H.P. piston junk ring bolts renewed. M.P. piston rod refitted to crosshead - (slack). H.P. bottom end brasses and M.P. bottom half and L.P. top half brasses reinstalled.

H.E. air pump rod skimmed; fwd. feed pump ram skimmed, forward bilge valve seats renewed. Independent circulating pump:- Top end pin and brasses renewed, bottom

end bearings reinstalled, cylinder bored, piston & rings renewed, piston rod (bent) renewed.

Cranksaft tried in lache & found true. Both independent main feed pumps, ballast and general service pumps overhauled - minor repairs. Independent auxiliary

feed pump water end renewed - (Was tied & holed at bottom); renewed water end

marked:- Lloyd's Test 500 LBS. 8.10.48. A.R.S. Tank and bilge valves overhauled, pipe lines

repaired as necessary, pumping arrangements tested. Auxiliary Condenser aft door renewed.

(see Continuation)
Sheet 3.

S.S. "AMERSHAM"
Repairs (Continued).

Steering engine main bearing brasses renewed, telemotor overhauled by Makers. Windlass top end pins and bushes and bottom end brasses renewed. Minor repairs effected to fan engine and dynamo engines. Exhaust steam interceptor cleaned. New oil fuel transfer pump discharge valve fitted to shell, starboard side of engine room, in accordance with the Rules.

B.S.: On account of tube leakage all plain tubes in both boilers have been renewed and stay tubes expanded and caulked. The centre furnaces in both boilers, found badly distorted, now renewed. (New furnaces marked Lloyds 3160 and 3170 d. 9. 48. E.E.) Starboard boiler wing furnaces, distorted, now jacked up a number of wasted c.c. stays and several wasted c.c. girder dog stays renewed; minor wastage of tube plates and on firebar line of furnace corrugations, water side, made good by E.W. where necessary and several c.c. rivets in both boilers renewed. Several other minor repairs effected in each boiler.

All boiler mountings overhauled, soot blowers fitted to each combustion chamber. On completion of repairs both boilers hydraulically tested and all found sound and tight.

The following additional machinery items have been fitted in vessel:-

New surface feed heater marked: Lloyds Test: Shell 440 lbs. Tubes 484 lbs. T.G. No 5108.

New Pressure feed filter, Caird & Rayner, marked: Lloyds D. 18397 Shell 560 lbs. 13.8.48. T.W.M.

Spare tail shaft marked: Lloyds 2472. J.C.B. 6.7.48.

Electrical Installation
2 — 12½ H.P. Generators.

The electrical installation examined under working conditions. Generators, cables and fittings examined. Navigation, accommodation, engine room and stokehold lighting wiring overhauled. Chart room, midship accommodation and after accommodation lighting wiring part renewed, 5 additional flood lights wired and fitted for masts and bridge space. On completion of repairs all circuits tested for insulation resistance, generators tested under load and governing and all found satisfactory.

Note:- D.G. coil, main cables, switch-board and junction boxes removed at this time.

Main and auxiliary machinery tried under working conditions and found satisfactory.

attached herewith:-

Newcastle Certificate No C. 27638 - Oil Fuel Heaters and Strainers

" " " C. 27415 Superheater Headers and Elements.


Sunderland " " C. 1211 Feed Heater.

London " " D. 18397 Pressure Feed Filter.

Leith Report " F. 2472. Spare Tail Shaft.

Glasgow Boiler Furnace Report dated 4.9.48.

D.L.Y.



Lloyd's Register
Foundation