

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 10<sup>th</sup> Nov 45 When handed in at Local Office 10<sup>th</sup> Nov 45 Port of Bordeaux  
No. in Reg. Book 06510 Survey held at Saint Nazaire Date, First Survey 5 Nov 1945 Last Survey 5 Nov 1945  
on the Machinery of the Wood, Iron or Steel Motor Vessel "COTENTIN" Year. Month. Nov 1945  
Tonnage Gross 2502 1/2 Vessel built at Newcastle By whom Hawthorn Leslie & Co. When 1934  
Net 11 1/2 Engines made at Yeonil By whom Petterson Ltd. When 1934  
Nominal Horse Power 105 Boilers, when made (Main) (Donkey)  
No. of Main Boilers 1 Owners Societe Charentaise de Navigation Owners' Address 67 rue Courcay Granville  
No. of Donkey Boilers 1 Managers Port Cherbourg Voyage  
Steam Pressure in Main Boilers 150 lb. If Surveyed Afloat or in Dry Dock Afloat quai S. Nazaire Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
in Donkey Boilers 150 lb.

Last Report No. 8243 Port Hav

## Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Copy of Damage Report sent to Owners.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

State date of examination of Screw Shaft

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Main Motor Damage, stated

to have been caused during the German occupation of the vessel during the years 1941 to 1944.  
Now found: N°3 cylinder opened out & completely examined: cylinder cracked at several places in way of the scavenging & exhaust orifices for a length of about 45". Cylinder out of service.  
Piston rings deformed & worn: out of service. Both connecting rod bottom end & brasses worn.  
to be remated: N°4 cylinder found cracked, but badly in the same places as N°3 cylinder: cylinder out of service. Piston cracked in way of cross head: condemned. Crank pin slightly corroded: to be skimmed up.

It was recommended to the Owners that both N°3 & 4 main motor cylinders be renewed before the vessel's leaving of Saint-Nazaire.

Spare pistons placed on board examined.

General Observations, Opinion, and Recommendation:— The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, H.B.M.S. 9, 11, & L.M.C. 9, 11, or R.M.C. 140 lb., E.D., &c.)

eligible, in my opinion to remain as classed, without fresh record

survey, subject to the N°3 & 4 cylinders be renewed before

the vessel leaves Saint-Nazaire.

Survey Fee (per Section 29) charge 4  
Special Damage or Repair Fee (if any) with damage  
(per Section 29.) Report  
Travelling expenses (if chargeable) 19

Fees applied for

Received by me

Committee's Minute

Assigned

Deferred

FRI. 14 DEC 1945

J. H. H. H.  
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

007714-007721-0234