



Repairs carried out on Motor N°1 7 Cylinders ALLEN:

Liners of cylinders N° 1-2-3-4-5-6-7 renewed and also all piston-rings.  
All New liners examined during progress at shop then tested under water pressure of 100 lb p  
sq. inch

All connecting-rods top bushes renewed

N° 3 top pin renewed

N° 5 main bearing remetalled

N° 3 bottom end brass renewed and spare one remetalled

Valves and seats smoothed on a special machine

On completion of repairs Main Engine and Auxiliary N° I Motor tested and examined under  
working condition. Found satisfactory.

DONKEY BOILER SURVEY-

As the vessel has only one D.B. to heat the accomodations and owing to the coldness of the  
winter the Owners request to postpone this survey till about may next when the season is better.

This request merits in my opinion favourable consideration of the Committee.

INTERIM CERTIFICATE Supplied (Copy of which herewith enclosed)

