

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel SS "MURISTAN"

Rpt. 51d.

No. 27715

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

nsverse No. 72

Depth "d" 20.7'

ming: Table No. 3

Description Bulb angle as approved.

gitudinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\text{10.03'}}{\text{20.7'}}$

Bridge Deck Sheerstrake .66" instead of .64' as approved.

the weight of ~~Stream~~ & Kedge Anchors (including stocks) is a few pounds lighter than required. In such case, but it is submitted the Anchors might be accepted.

other respects.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to

be classed 100 A.1. (steel)

1 Dk. (steel).

Cell DB 278' 7495. FPT 1135. APT 1225.

FK. 5BH. Com. Lloyd's A.G.C.P. P 33', B 28', F 28'.

M *atb*
29-1-20

It is concluded the thickness of Bridge sheerstrake is as given in report & as in sister vessels & not as shown on plan of midship section as built, forwarded with report, but the Surveyors should be requested to state if this is so.

The Surveyors should also state whether the Oil Fuel in Double bottom is for burning only, or for carrying cargo.