

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MAY - 2 1940

DECLASSIFIED

RAY No.

Date of writing Report 26/4/40. When handed in at Local Office 26/4/40. Port of GENOA.

No. in Survey held at GENOA. Date, First Survey & Last Survey 25/4/40. (No. of Visits 19)

23402 on the Machinery of the WORLD TRAVEL Steel Sc. "DONIZETTI" Year. Month.

Tonnage } Gross 2428 Vessel built at Monfalcone By whom Cant. Nav. Triestino When 1928/12
Net 1420

Engines made at Trieste By whom Stabilimento Tecnico When 1928

Boilers, when made (Main) (Donkey) 1928

Owners "Tirrenia" Soc. Anon. di Nav. Owners' Address (if not already recorded in Appendix to Register Book.)

Managers (if not already recorded in Appendix to Register Book.) Port Fiume Voyage --

If Surveyed Afloat or in Dry Dock Afloat Gen. Harbour Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Donkey Boilers 100 lb.

CHARACTER, Date of last Survey and of Periodical Surveys.	Years assigned have expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A.I.		* L.M.C. CS. 3-37
1-40		1-39
SS. Fiu. N° 2-36		DBS. 11-39
		CL. 2-37

Particulars of Examination and Repairs (if any) ADV. L.M.C. C.S.

Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Has a damage report made by anyone else? If so, by whom? No

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? No

What parts of the Boilers could not be thus thoroughly examined? D.B.S. not due.

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

What is the latest date of internal examination of each boiler? -

Did the Surveyor examine the Safety Valves of the Main Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? -, and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? -, and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? -, and of the Donkey Boilers? -

Has the screw shaft now been drawn and examined? No Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

Has the shaft now been changed? - If so, state reasons - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

What is the date of examination of Screw Shaft? - State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. Vessel afloat.

Engine parts, when referred to by numbers, should be counted from forward. - Is electric light and/or power fitted? -

Did the Surveyor examine the generators, motors, switchgear, cables and fuses? -

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? -

Is the Survey complete, state what arrangements have been made for its completion and what remains to be done. It was stated that the L.M.C. C.S. will be advanced from time to time in accordance with Circular N°1670.

Work Done - FOR ADVANCEMENT OF L.M.C. C.S. Examined the following machinery parts:-

Main Engine - N°1 piston together with cylinder, cover and valves, piston rod, crosshead with its top end bearing brasses, guides and connecting rod.

All found in good condition.

N.B. No Interim Certificate was issued in this case but a note of the machinery parts now examined was made in a book kept aboard by the Chief Engineer.

General Observations, Opinion, and Recommendation: The machinery of this vessel, so far as now

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, D.S.M.S. 2, 11, & L.M.C. 2, 11, or CS 2, 11, &c.)

seen, is in good condition, and the vessel is eligible, in my opinion, to remain as classed with fresh

record of * L.M.C. C.S. (with date) when the survey has been completed.

Pt L.M.C. CS. Lit. 100.-

Survey Fee (per Section 29) £ 35.- Fees applied for 27/4/40.

Special Damage or Repair Fee (if any) £ - Received by me, [Signature]

Travelling expenses (if chargeable) £ - 19 40

Committee's Minute TUE. 14 MAY 1940

Assigned 4 As now [Signature]

Engineer-Surveyor to Lloyd's Register of Shipping.



...of

ADVOZED

04/4/75

IT T E S I X O

ADVOZED

04/4/75

© 2020

Lloyd's Register Foundation

... ..

... ..

... ..

... ..

... ..

... ..

Advanced.

Schaps Summary due 240

9/1/70

04/4/75

75

001.711.80.0MI 79

...