

Rpt. 9.

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

22 MAR 1950

N0471

Date of writing Report 13 MAR 1950 When handed in at Local Office 13 MAR 1950 Port of LIVERPOOL
 No in Reg. Book. Survey held at Liverpool Date. First Survey Y Last Survey 5/3/1950
 29349 on the Machinery of the WOODLARK Steel S.S. "ULSTER CASTLE" (No. of Visits 1)

Tonnage { Gross 1217 Vessel built at Glasgow By whom W. Beardmore & Co. Ltd. Year. Month. 1920 4
 Net 512 Engines made at -do- By whom -do- When 1920
 Nominal Horse Power { 265 Boilers, when made (Main) 1920 (Donkey) 1920 When 1920
 Owners Belfast S.S.Co.Ltd. Owners' Address (if not already recorded in Appendix to Register Book.)
 No. of Main Boilers 2 Managers - Port Belfast Voyage -
 No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock 49
 Steam Pressure in Main Boilers 175 (State name of Dock) Banning Dock
 in Donkey Boilers 70

Last Report No. 129522 Port Liv.

Particulars of Examination and Repairs (if any) Special Examination

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? no

" " Donkey " " no

not, state for what reasons BS not due What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓

Did the Surveyor examine the Safety Valves of the Main Boilers? ✓ Present condition of funnel(s) ✓

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? ✓ Has it a continuous liner? ✓ Is an approved oil retaining appliance fitted at the after end? ✓

Has the shaft now been changed? ✓ If so, state reasons ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft ✓

Is electric light and/or power fitted? ✓ State the wear down in the term bush ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Engine parts, when referred to by numbers, should be counted from foreward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

At the request of the Owners Superintendent examined tubes in both main boilers with a view to postponing the renewal of the stoppered tubes until the end of May 1950 when it is proposed to withdraw the vessel from service.

Found the general condition of the tubes in the main boilers, including the stoppered ones, is such that the vessel is serviceable until the end of May 1950. (Attached sketch showing stoppered tubes)

The Donkey Boiler was examined under steam and found satisfactory, with 2 stoppered tubes.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, LMC 9,11 or LMC 140 lb., FD, &c.)

The machinery of this vessel, as now seen, is in good condition and eligible in my opinion to remain as now classed with fresh record B.S. 5.49 when defective tubes in main and Donkey Boilers have been renewed and subject to tests as previously recommended.

Survey Fee (per Section 20) £ 3 3 0
 Special Damage or Repair Fee (if any) £ 5 5 0
 SUMOAT FEE £ 2 6
 Travelling expenses (if chargeable) £ 2 6

Fees applied for 14 MAR 1950

Received by me, A. Bedford

Committee's Minute LIVERPOOL 21 MAR 1950

Assigned Deferred for boiler repairs etc.

FRI. 26 MAY 1950

Deferred

Wise gain upholding

Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book.

5200-48800-58800

Is a certificate required? If so, to be sent to

FRI. 16 JUN 1950

Record

Omit all

Phoned
amendment
to Lloyd's
30/6 A.B.

Further broken

particulars on copy
reprint of

write to R.D.

(note re sale
L.C.C.)

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page. Some words like "Lloyd's" and "amendment" are faintly visible.]

JUN 22 1950