

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

14 NOV 1927

Date of writing Report 19/10/27 When handed in at Local Office 19/10/27 Port of GENOA
 No. in Reg. Book 31006 Survey held at GENOA Date, First Survey 21/6/27 Last Survey 18/10/27 (No. of Visits 12)
 Tonnage Gross 11920 Net 11920 Vessel built at Baia By whom Cant.ed Off. Meridionali When 1927
 Engines made at Trieste By whom Stab. Tec. Triestino When 1927
 Boilers, when made (Main) Oil Engines. (Donkey) -
 Owners' Address Nav. Gen. Italiana (if not already recorded in Appendix to Register Book).
 Port Genoa Voyage -
 No. of Main Boilers Oil Eng. Managers -
 No. of Donkey Boilers - Surveyed Afloat or in Dry Dock
 Steam Pressure in Main Boilers - (State name of Dock.)
 in Donkey Boilers -

Last Report No. Port Particulars of Examination and Repairs (if any) 1st ENTRY LMC.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Is a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

Is was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the Surveyor examine the Safety Valves of the Main Boiler?

the Surveyor examine the Safety Valves of Donkey Boiler?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

the Surveyor examine the drain plugs of the Main Boilers?

the Surveyor examine all the mountings of the Main Boilers?

screw shaft now been drawn and examined? Is it fitted with continuous liner?

shaft now been changed? If so, state reasons

the shaft now fitted been previously used? Has it a continuous liner?

the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done?

SEE HAMBURG REPORT No. 17044.

NOW DONE:- Two Vertical Boilers Nos. 442 and 444 have now been satisfactorily fitted in place on board. They have been examined under steam and their safety valves adjusted to 100 lb. per sq. in. An accumulation test has been held and all found satisfactory. Sizes of compression springs are as follows:-

Port Boiler	Starboard Boiler
F.15 m/m A.15 m/m	F.19 m/m A.23 m/m.

The steam, feed and oil fuel pipes have all been tested to Rule requirements. On completion all installations examined under test and working conditions and all found satisfactory.

General Observations, Opinion, and Recommendation:- The above is for the information of the Committee and should be attached to Hamburg Report No. 17044.

Survey Fee (per Section 29) £ 19
 Special Damage or Repair Fee (if any) (per Section 28.) £ -
 Travelling Expenses (if chargeable) £ -

Committee's Minute Assigned

FRI. 18 NOV 1927

TUE. 23 APR 1929

Engineer Surveyor to Lloyd's Register of Shipping.



© 2021

008322-008332-0254

Lloyd's Register Foundation