

Rpt. 8.

(Received at London Office 16 JAN 1950)

No. 17434

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 10-1-1950

When handed in at Local Office 10-1-1950

Port of Genoa

No. in Reg. Book.

Survey held at Genoa

Date, First Survey 24-12-49

Last Survey 29-12-1949

1949

26297 on the Wood, Iron or Steel Twin Sc M/V Sobieski

(No. of Visits 6)

TONNAGE :-

GROSS 11030

UNDER DK 7344

NET 6351

Built at Newcastle

By whom Swan Hunter &amp; Wigham Richardson Ltd

YEAR 1939

MONTH 5

Owners Edynia America Shipping Lines Ltd

Owners' Address

(If not already recorded in Appendix to Register Book)

Managers

Port belonging to Edynia

Surveyed Afloat or in Dry Dock?

Name of Dock Crazie N°3

Destined Voyage Genoa-South America

CeLDorDBa feet; uE&B feet; f feet  
total capacity tons. FPT tons; APT tons; MT tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 4416 Port Nap.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and Items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements)

CHARACTER * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
* 100A1 with freeboard 649. SS GdY 447	* LMC CS 348 348 DBS 1148 TS. 61.10.46. Ref. Mely

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

docking &amp; repairs

Now done for

1) Docking

Vessel placed in dry dock. Bottom and rudder cleaned examined and recoated. Weather decks, hatchways, hatchcovers, ventilators & their coaming, steering arrangements etc examined.

2) Repairs

Upper part of rudder plating corroded & cracked in way of welding now drilled & gauged and found of satisfactory thickness; cracked welds weed out, reworked and doublings in way fitted by EW.

SUMMARY OF DAMAGE REPAIRS :-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...	/	/	/	/	/	/	/	/
Removed and Fairled or Repaired	/	/	/	/	/	/	/	/
Fairled or Repaired in place	/	/	/	/	/	/	/	/

PRESENT CONDITION OF THE

Decks good	Bulkheads	Engine Room Skylights good	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Celling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats good
Beams & Fastenings	Rudder good	Scuppers good	Masts, Yards, &c.
Outside Plating good	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained from deck
" " in way of sidelights	Windlass	Hatches	(State if wedges removed.)
Frames	Have pumps been examined and found efficient?	Planking	Equipment letter 81
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Anchors, No. of 38 + 15
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged) 10
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" length stated mean diamr. complete
Floors	Air and Sounding Pipes good	Transoms, Pointers & Crutches	" Rule length 320 size 2 1/16
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Chain Locker
Stringers		" " at other places	Hawsers & Warps stated complete
Inner Bottom Plating		Stringers, Clamps & Shelves	Standing and Running Rigging good
Have the Tanks been examined internally? no		Salting	Sails
Have the Tanks been tested? no		State if examined.	

General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel as now seen, is, in my opinion worthy to be continued as classed with fresh record of docking 1249 Gen

examine next dry docking?

Survey Fee (per Section 29) docking Lt 10950. =

Fees applied for,

Special Damage or Repair Fee (if any) Lt 31300. =

11. 1. 1950

(per Sec. 29)

CAN FUND - 1.250. =

Received by me,

Travelling Expenses (if chargeable)

HOLIDAY FEE - 8.900. =

19.

Second Surveyor's Fee (if any)

REV. TAX 1.632. =

Committee's Minute

WED 15 FEB 1950

Character Assigned

12. 49 Gen without spl chn

Bath S. 12. 49

DBS 1.50

date &amp; Note Gen

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

008446-008454-0026



S.R.L. N° 106 Rudder pttg now repaired (see above)

Fluor

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

[illegible]

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.