

Rpt. 8.

(Received at London Office)

No. 1888

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 1st Feb., 1954. When handed in at Local Office FEB - 4 1954. Port of Kobe
 No. in Survey held at Kobe Date, First Survey 22nd Jan., Last Survey 29th Jan., 1954.
 Reg. Book 355508 on the M.V. "HIYEHARU MARU" (No. of Visits 4)
 TONNAGE: — Built at Kobe By whom Mitsubishi H.I. Reorganized Ltd.
 GROSS 7850 7846 Owners Shinnihon Kisen K.K. Owners' Address Nishinomiya
 UNDER DK. 6880 6878 Managers Port belonging to
 NET 4420 4436

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Mitsubishi, Kobe Destined Voyage
 Cell DBor DBa feet: uE&B feet: f feet: f
 total capacity tons. FPT tons: APT tons: MT feet: tons.
 Only alterations in the existing records of tanks should be inserted.
 N.B. — All alterations in the existing records should be underlined.

Last Report, No. 1440 Port Kobe

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR Damage Repairs necessary consequent upon Heavy Weather

encountered on voyage from Los Angeles to Yokohama on January 10th 1954. A particularly heavy sea stove in No.1 Hatch, two hatch beams being severely buckled resulting in the collapse of the wood covers into the hold. After coaming of No.1 Hatch buckled and deck and girders below in way set down. S.S. bulwark set inboard and two stays buckled. Forecastle Front S.S. set in in way of bulwark bracket.

DONE: — Hatch beam scantlings checked and found in order. Lightening holes in all beams compensated and two beams renewed. Hatch beam rests rebuilt as indicated below. After coaming removed, faired and refitted. Deck and girders below released and faired. S.S. Bulwark faired and stays removed faired and refitted. Forecastle front faired and bracket extension fitted to line of vertical stiffener. Docking for purpose of renewing the rudder stock consequent upon rudder contact with quay wall resulting in a twist of 20° in the stock. Test Certificate in respect of the new stock attached hereto. Upon completion, gear tested under sea conditions and found in good order. Vessel placed in drydock, bottom & rudder cleaned, examined and coated. (P.T.O.)

MARY OF DAMAGE REPAIRS: —	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items: —
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Good	Bulkheads	Not examined	Engine Room Skylights	Good	Copper, or Y.M. (State if on Felt.)			
"	Ceiling	"	Coal Bunkers, Openings, Covers, &c.	"	When fitted, Month	Year		
"	Cement or Asphalt	"	Oil Bunkers	Not examined				
"	Rudder	Good	Scuppers	"	Boats	Good		
"	Steering gear and its connections	Good	Cargo Hatchways	Good	Masts, Yards, &c.	Good		
"	Windlass	Good	Hatches	"	Condition, how ascertained (State if wedges removed.)	From deck		
"	Have pumps been examined and found efficient?	No	Planking		Equipment letter	Stated		
"	Have Sluice Valves been examined and found efficient?	No	Caulking		Anchors, No. of	complete		
"	Have Watertight Doors been examined and found efficient?	No	Treenails		Cables (State if now ranged)	" length mean diamr. (on board.)		
"	Have Ventilators and their Coamings been examined and found efficient?	Yes	Breasthooks & Stemson		" Rule length size	Chain Locker	Not examined	
"	Air and Sounding Pipes	Not exd.	Transoms, Pointers & Crutches		" at other places	Hawser & Warps	Sufficient	
"	Doubling Plates under Sounding Pipes	"	Timbers of Frame at openings		Stringers, Clamps & Shelves	Standing and Running Rigging	Efficient	
"			Sanding	State if examined	Sails			

Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example: — "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1.38."

This vessel, is eligible, in the opinion of the undersigned to remain as now classed without record of survey and with drydocking date 1.54.

per Section 23) £ 15,000
 Special Damage or Repair Fee (if any) £ 10,000
 Travelling Expenses (if chargeable) £ 1,500.
 Second Surveyor's Fee (if any) £
 Committee's Minute
 Character Assigned 1.54 Kob.

Fees applied for, FEB - 4 1954
 Received by me, 19

Refined Hiron & M. Kamakura
 Surveyor to Lloyd's Register of Shipping.

008765-008772-0139

Lloyd's Register
 Foundation

CLEAR

Is Certificate required? If so, to be sent to

Interim Certificate No.C-17831 issued, copy attached hereto.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

Number of Certificate.	Anchors. ^a	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested & Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream																
	Kedge																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]