

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.)

Date of writing Report October 24 1945 When handed in at Local Office October 24 1945 Port of FALMOUTH.
No. in Reg. Book Survey held at FALMOUTH. Date, First Survey SEPTEMBER 18TH Last Survey SEPTEMBER 18TH 1945
07219. on the Machinery of the ~~Wood Iron~~ Steel SS "EMPIRE FULHAM" (No. of Visits ONE)

Tonnage { GROSS 222 Vessel built at NORTHWICH. By whom W.T. YARWOOD & SONS (1935) LR Year. Month. When 1944 10TH
Net 77 Engines made at NORTHWICH. By whom W.T. YARWOOD & SONS (1935) LR When 1944
Nominal Horse Power 57 MW Boilers, when made (Main) 1944 (Donkey) ✓
No. of Main Boilers 1 SB Owners MINISTRY OF WAR TRANSPORT. Owners' Address Port LIVERPOOL Voyage HARBOUR DUTIES.
No. of Donkey Boilers ✓ Managers T. PHELAN & CO. LD. (if not already recorded in Appendix to Register Book.)
Steam Pressure in Main Boilers 140 lb If Surveyed Afloat or in Dry Dock In No 2 Dry Dock (GUYER/EXP/CP) Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
in Donkey Boilers ✓ (State name of Dock.)

Last Report No. _____ Port _____
Particulars of Examination and Repairs (if any) CONDITION.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside the Main Boiler separately and make a thorough examination at this time? No

" " Donkey " " " ✓

If this was not done, state for what reasons? BOILER NOT DUE FOR SURVEY.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓ Present condition of funnel(s) ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine the drain-plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? YES

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between bearing metal of stern bush and top of after bearing of screw shaft CLOSE.

Engine parts, when referred to by numbers, should be counted from foreward. Is electric light and/or power fitted? ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done COMPLETE.

Now Done for Condition.
Vessel placed in dry dock. Propeller, oil gland (externally), aft end of stem tube examined & all found to be in good order.
Sea connections opened up & examined together with their inside & outside fastenings & all found to be in good order.

General Observations, Opinion, and Recommendation:— The machinery of this vessel as far as has been seen, is in an efficient condition & eligible in my opinion to remain as now classed without fresh record of survey.
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0,11, B.S.M.S. 0,11, & L.M.C. 0,11, or X L.M.C. 140 lb., F.D., &c.)
CS 2,24.

Survey Fee (per Section 20) £ : : Fees applied for 19
Special Damage or Repair Fee (if any) (per Section 20.) £ : : Received by me, 19
Travelling expenses (if chargeable) £ : :
TUES. 6 NOV 1945
Assigned ITS own

J. P. Owen 2020
Engineer Surveyor to Lloyd's Register of Shipping.
Lloyd's Register Foundation

Index Character of Ship and Machinery generally, as in the Register Book

Is a Certificate required? If so, to be sent to

It is submitted that this
vessel is eligible to remain
as CLASSED.

L.J.
29/10/45.

[Faint, illegible handwritten text, possibly a signature or reference number]

[Faint, illegible handwritten text, possibly a list or notes]

[Faint, illegible handwritten text]

[Faint, illegible handwritten text]