

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office)

18 JUL 1949

Date of Report, Report 23/6/49 When handed in at Local Office 23/6/49 Port of Rio de Janeiro  
 No. in Survey held at Rio de Janeiro Date First Survey 9/6/49 Last Survey 23/6/49 No. of visits 2  
 Reg. Book 60929 on the Machinery of the ~~Wood, Iron~~ Steel steamer "GUARAPUAVA"

Gross 590 Vessel built at Aberdeen By whom J. Duthie Torry SB Co When 1920 - 2  
 Tonnage Net 293 Engines made at Mdb. By whom Richardsons, Westgarth & Co. Ltd.  
 Nominal 88 MN Boilers, when made (Main) - (Donkey) -  
 Horse Power No. of Main Boilers 1SB Owners Emp. Internacional de Transportes Ltda.  
 No. of Donkey Boilers - Managers Santos  
 Steam Pressure in Main Boilers 180 lb Particulars of Classification (which must be inserted in Register Book & Supplement)  
 in Donkey Boilers - If Surveyed Afloat or in Dry Dock - Dry Dock - Ilha das Cobras

Last Report No. Port

## Particulars of Examination and Repairs (if any) Gen. Exam. and BS

For the purpose of this survey, the vessel was examined in detail and a report made in the terms of the Rules. It is clearly the duty of the Surveyor to report on the condition of the vessel and the nature and extent of any repairs required. Repairs are required in the case of the vessel, and the nature and extent of the repairs required are stated in the report. The dates and initials of the Surveyor are also stated in the report.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

Donkey " "

If not, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to ensure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. 9/6/49

Present condition of engine X good

Did the Surveyor examine the Safety Valves of the Main Boilers? yes

To what pressure were they afterwards adjusted under steam? 180 lbs.

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

yes

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

yes

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? no

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has the screw shaft now been changed? If so, state reasons

no

State date of examination of Screw Shaft

State the wear down in the

Wear down 1/8"

Is electric light xxxxxxxx fitted? yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? generally

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

yes

Engine parts, when referred to by numbers, should be counted from forward. The owners state that the vessel will be returned to this port about the end of September next when a complete machinery survey will be carried out. This in accordance with the Secy's letter of the 11th April 1949.

Now Done. Vessel in drydock.

Boiler examined internally and externally complete with safety valves, doors and mountings.

Boiler examined under steam and the safety valves adjusted to the above stated pressure.

The owners representative and the C/Engineer state that the machinery is giving satisfactory service. This was examined generally without opening up. The electrical installation examined generally and megger tested satisfactorily. Examined the propeller and outside fastenings of underwater fittings.

## General Observations, Opinion and Recommendations The machinery of this vessel is eligible, in my

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, subsequent upon this survey, and also any alterations required to be made in the records of the vessel's machinery, boilers, working pressures, etc. due to repairs, alterations, etc. made during the survey.)

opinion, to be continued as classed with fresh record of BS 6.49, subject to the complete machinery survey being commenced before the end of October 1949.

Survey Fee (see Section 25) Gen. Exam. BS 1.200,00

23/6/49

Special Damage or Repair Fee (if any)

Received by me,

Assessing expenses, etc. (see Section 25)

50,00

Committee's Name

FRI. 22 JUL 1949

Assigned



© 2020

Lloyd's Register Foundation